

50-263

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

TO: Mr. D. K. Davis

FROM: NSP
Minneapolis, Minnesota 55401
L. O. MayerDATE OF DOCUMENT
09/01/77DATE RECEIVED
09/06/77☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☐ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1cc

DESCRIPTION Furnishing correction to page 3 of the second sentence of the second paragraph to revised report submitted 08/03/77 concerning the Reactor Vessel Material Surveillance Program...

ENCLOSURE

1p

DO NOT REMOVE

ACKNOWLEDGED

DISTRIBUTION FOR MATERIAL ON REACTOR VESSEL
DATA PER R. INGRAM 5-26-77

PLANT NAME: MONTICELLO

jcm 09/07/77

SAFETY

FOR ACTION/INFORMATION

BRANCH CHIEF: (7) DAVIS
~~PROJECT MANAGER:~~
~~LIO. ASST:~~
ZWETZIG

INTERNAL DISTRIBUTION

~~REG FILE~~
NRC PDR
I & E (2)
OELD
MIPC
HANAUER
PAWLICKI
EISENHUT
SHAO
BAER
BUTLER
GRIMES
HAZELTON
HOGE
R. GAMBLE
RANDALL

EXTERNAL DISTRIBUTION

LPDR: Minneapolis, MN
TIC
NSIC
ACRS 16 CYS SENT CATEGORY B

CONTROL NUMBER

MUN 4
772500059 B

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

September 1, 1977

Regulatory

File Cy



Mr D K Davis, Acting Chief
Operating Reactors Branch No. 2
Division of Operating Reactors
c/o Distribution Services Branch, DDC, ADM
U S Nuclear Regulatory Commission
Washington, D C 20555

Dear Mr Davis:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Corrected Information on
Reactor Vessel Material Surveillance Program

Our letter to you dated August 3, 1977 provided you with a revised report describing the General Electric BWR Reactor Vessel Material Surveillance Program. Page 3 of this report contained a typographical error. The second sentence of the second paragraph on page 3 should be corrected to read:

The shielded metal arc welds, electroslag welds, and submerged metal arc welds made without copper coated electrodes would exhibit approximately a 10 to 15 OF variation in transition temperature response due to residual element composition at the maximum 1/4T end-of-life fluence expected for BWR/2, 3 and 4 plants.

Please make this revision to all copies of our August 3, 1977 report.

Yours very truly,

A handwritten signature in cursive script, appearing to read 'L. O. Mayer'.

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/ak

cc: J G Keppler
G Charnoff
MPCA - Attn: J W Ferman

772500059