

*Central
Files*

NSP

N O R T H E R N S T A T E S P O W E R C O M P A N Y

August 26, 1980

Mr. James G. Keppler
Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:


MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

The following is submitted in response to IE Bulletin No. 80-19, Revision 1:

There are no mercury-wetted relays used in the Reactor Protection System at the Monticello Nuclear Generating Plant.

An estimated seven manhours were expended in the preparation and review of the report required by this bulletin.

Yours truly,


For D. E. Gilberts
Vice President
Power Production

cc: Mr. G. Charnoff
Director, Division of Reactor Operations Inspection
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

DEG:nk

AUG 29 1980

8009110 499

Q