



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500



May 6, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137


MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

HPCI-10 Disc Pin Failure

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.1.e since it represents a condition which might have prevented operation of the HPCI system.

Yours very truly,



L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA

Attn: J W Ferman

A002
S
11/1

-over-

8105110224

5

MAY 6 1981

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08 | _____ 8

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	3
---	---

7 3 0

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA	(39)			

7		8		9		10		11		12			
LOSS OF OR DAMAGE TO FACILITY								(43)					
TYPE		DESCRIPTION											
1	9	Z	(42)	NA									

7 8 9 10
 PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N (44) NA
 7 8 9 10
 NRC USE ONLY

7 8 9 10
8105110228
NAME OF

NAME OF PREPARER

W. Overlid

PHONE: (612) 295-5151

NRC USE ONLY

100