

*Central Mail
& Files*

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
DAEC - 76 - 257

August 16, 1976

Mr. James G. Keppler, Director
Office of Inspection and Enforcement-Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Prompt Notification of a
Reportable Occurrence

File: A-118a

Dear Mr. Keppler:

This letter, telecopied to your office, is intended to satisfy the requirement for prompt notification of a Reportable Occurrence in accordance with Specification 6.11.2.a of the Duane Arnold Energy Center Technical Specifications.

Technical Specification paragraph(s) violated: 3.2.B

Description Occurrence: During the performance of the Surveillance Test 42B018 the annunciator card for FDIS-2139 was found pulled. This alarm detects a broken core spray line between the reactor vessel wall and core shroud.

Very truly yours,



G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

DLW/GGH/mg

76-51

Director, Management Information and Program Control (2)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Received 9:15 8/17/76 je