

L-3

06-30610-01  
03035611Attention:  
Laurie A. Kauffman  
Leak Test

## LEAK TEST CERTIFICATE

Wipe Date 10/3/11

## DESCRIPTION OF DEVICE/SOURCE

Model C-300 Ser 21011  
 SOURCE 1 SOURCE 2  
 Material CS 137 Am 241:Be  
 Source Ser .3 GBq 1.48 GBq  
 RSO Name Phil Pelilla  
 Telephone (203) 996-8800

Do Not Write In This Space  
For HSI Use Only

## REMOVABLE ACTIVITY

Beta/Gamma Alpha  
0 uCi 0 uCi  
 Humboldt Scientific  
 By DOTV  
 Date 10/10/11

## Instructions

- 1 Use wipe procedures as described in the device manual.
- 2 Enter all information under description.
- 3 Print or type return address in the space provided.
- 4 Wipe source(s) and put filter paper in the plastic bag.
- 5 Keep the middle copy and mail this form and bag to Humboldt.
- 6 Regulations require that sources with removable activity greater than 0.005 uCi be removed from service for repair and decontamination or disposal. Authorities must be notified.

5200174

Return  
Address  
Label  
Please  
Type or  
Print  
Clearly

- Q/C Resource Technical Services  
 - 3 Simm Lane  
 - Newtown, CT 06470

HUMBOLDT SCIENTIFIC INC. 551D Pylon Drive, Raleigh, NC 27606, (919) 832-6509

REC'D IN LAT 1/30/12576646  
NMSS/RGN1 MATERIALS-002