



Fisher Controls International LLC

205 South Center Street
P.O. Box 190
Marshalltown, IA 50158
USA

T (641) 754 3011
F (641) 754 2830

January 16, 2012

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555-0001

Subject: 10 CFR 21.21 (a)(2) Interim Notification
Possible Disc Pin Engagement Issue on Type A11 Butterfly Valve

Pursuant to 10 CFR 21.21(a)(2), Fisher Controls International LLC ("Fisher") is providing the required written final notification of a possible deviation or failure to comply.

On December 13, 2011, Fisher provided an interim notification of a possible deviation or failure to comply concerning a possible issue with the disc pin engagement of a 20" Type A11 Butterfly Valve, Serial Number 19102243. The affected valve was returned to Fisher for evaluation and correction and, upon correction, was returned to the customer on November 21, 2011.

Fisher has completed the review of the valve design and has determined that this potential issue would not have negatively affected the subject valve or its performance. Therefore, Fisher will not be issuing a notification per the requirements of 10 CFR 21 21.21(b).

A handwritten signature in black ink, appearing to read "Ed Merwald".

Ed Merwald
Vice President, Engineered Products Business Unit
Emerson Process Management, Fisher Valve Division

Reference: NRC Event Number 47521



IE19
MRR