



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
1600 EAST LAMAR BLVD
ARLINGTON, TEXAS 76011-4511

February 27, 2012

MEMORANDUM TO: Eric J. Leeds, Director
Office of Nuclear Reactor Regulation

FROM: Elmo E. Collins **/RA/**
Regional Administrator
Region IV

SUBJECT: COLUMBIA GENERATING STATION LICENSE RENEWAL
APPLICATION

On January 20, 2010, Energy Northwest requested to renew the operating license for their Columbia Generating Station in accordance with 10 CFR Part 54. With close coordination and support from your staff in the Division of License Renewal, we completed the inspections at Columbia Generating Station, in accordance with the guidance in Inspection Manual Chapter 2516 and Inspection Procedure 71002. The inspections verified that Energy Northwest implemented the scoping methodology and established aging management programs in conformance with the descriptions contained in the Energy Northwest application for license renewal. Sampling inspections verified: (1) reasonable assurance of the acceptability of the existing and planned aging management programs, and (2) the applicant provided the required documentation in an auditable and retrievable form. The inspection identified some issues that the applicant resolved satisfactorily. We documented our inspection results in NRC Inspection Report 05000397/2010007, dated December 17, 2010 [ML103540496].

We have determined that Energy Northwest has completed or will have completed programs and activities related to the license renewal of Columbia Generating Station in substantial agreement with docketed commitments and regulatory requirements. Within the above inspection scope, Energy Northwest demonstrated the capability to manage the effects of aging during the period of extended operation. Therefore, we conclude that there is reasonable assurance that the Energy Northwest aging management programs provide an adequate foundation for renewing the license for the Columbia Generating Station for an additional 20 years.

Should you have any questions concerning this letter, please contact me at (817) 200-1225.

Docket: 50-397
License: NPF-21

Electronic distribution by RIV:

Regional Administrator (Elmo.Collins@nrc.gov)

Deputy Regional Administrator (Art.Howell@nrc.gov)

DRP Director (Kriss.Kennedy@nrc.gov)

DRP Deputy Director (Troy.Pruett@nrc.gov)

DRS Director (Anton.Vegel@nrc.gov)

DRS Deputy Director (Tom.Blount@nrc.gov)

Branch Chief, Engineering Branch 2 (Geoffrey.Miller@nrc.gov)

Senior Resident Inspector (Jeremy.Groom@nrc.gov)

Resident Inspector (Mahdi.Hayes@nrc.gov)

Branch Chief, DRP/A (Wayne.Walker@nrc.gov)

Senior Project Engineer, DRP/A (David.Proulx@nrc.gov)

Project Engineer, DRP/A (Jason.Dykert@nrc.gov)

Site Administrative Assistant (Crystal.Myers@nrc.gov)

Public Affairs Officer (Victor.Dricks@nrc.gov)

Public Affairs Officer (Lara.Uselding@nrc.gov)

Project Manager (Mohan.Thadani@nrc.gov)

Acting Branch Chief, DRS/TSB (Ryan.Alexander@nrc.gov)

RITS Coordinator (Marisa.Herrera@nrc.gov)

Regional Counsel (Karla.Fuller@nrc.gov)

Congressional Affairs Officer (Jenny.Weil@nrc.gov)

Division of License Renewal Project Manager (Arthur.Cunanan@nrc.gov)

RidsNrrDlrResource

RidsNrrDlrRpb1 Resource

RidsNrrDlrRpb2 Resource

R:_REACTORS_COL\2012\CGS LR REC Letter-GAP

ADAMS ML12058A496

ADAMS: <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> SUNSI Review Complete		Reviewer Initials:
		<input type="checkbox"/> Publicly Available		<input checked="" type="checkbox"/> Non-Sensitive
		<input type="checkbox"/> Non-publicly Available		<input type="checkbox"/> Sensitive
SRI:EB2	C:EB2	C:DRP/A	D:DRS	RA
GPick/tek	GMiller	WWalker	AVegel	EECollins
/RA/	/RA/	/RA/	/RA/	/RA/
02/21/12	02/21/12	02/23/12	02/27/12	02/27/12

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax