

December 2, 2010

MEMORANDUM TO:

David C. Lew, Director
Division of Reactor Projects

Darrell J. Roberts, Director
Division of Reactor Safety

FROM:

Arthur L. Burritt, Chief /RA/
Projects Branch 3
Division of Reactor Projects

Richard Conte, Chief /RA/
Engineering Branch 1
Division of Reactor Safety

SUBJECT:

SEABROOK CONCRETE INSPECTION / ACTION PLAN

Outside of Scope

outside of scope

Enclosures:

- 1: Summary of Concrete Condition Assessment
- 2: Seabrook Building Concrete NRC Inspection / Action Plan
- 3: NRC Walkdown of Building Groundwater Infiltration

Information in this record was deleted
in accordance with the Freedom of Information
Act, exemptions outside of scope
FOIA- 2012-01109

9/3

ENCLOSURE 1

Summary of Seabrook Concrete Condition Assessment

Outside of Scope

outside of scope

NRC Staff Next Steps: (1) Immediate safety review (done), (2) follow NextEra ongoing operability assessments, (3) PIR sample, (4) LR RAI, (5) LR inspections (6) TIA to evaluate need for technical input on building dynamic response due to degraded concrete conditions.

Out of Scope

ENCLOSURE 2
Seabrook Building Concrete
NRC Inspection / Action Plan

Updated: 12/2/10

Outside of Scope

outside of scope

Outside of Scope

(4 pages)

Out of Scope

Outside of Scope

outside of Scope

William J. Raymond
SRI – Seabrook

Suresh Chaudhary
Engineering Branch 1, Region I

Brooke Traynham
LLW Branch, FSME

out of Scope

Table 1 - Seabrook Concrete Assessment Inspection / Action Plan

Outside of Scope

outside of scope

Outside of Scope

(2 pages)

Act of Scope

ENCLOSURE 3

NRC Walkdown of Building Groundwater Infiltration

Outside of Scope

outside of Scope

Outside of Scope

(3
pages)