

FEB 20 1987

License: 35-00502-02
35-00502-05

Docket: 30-05900/87-01
30-20094/87-01

Halliburton Company
1015 Bois D'Arc
Duncan, Oklahoma 73536

Gentlemen:

Enclosed please find NRC Inspection Report 30-05900/87-01 and 30-20094/87-01 documenting the enforcement conference held on January 26, 1987. The enforcement conference was held to review the findings of the NRC inspection conducted at your facility December 8-12, 1986, and to obtain your response to these findings. Enforcement correspondence concerning these matters will be sent to you under separate cover.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

Original Signed By:
WILLIAM L. FISHER

William L. Fisher, Chief
Radiological and Safeguards
Programs Branch

Enclosure:
Appendix - NRC Inspection Report
30-05900/87-01 and 30-20094/87-01

bcc:
DMB - Original (IE-07)
RDMartin
RLBangart
WLFisher
*DWeiss, LFMB (AR-2015)
*Inspector
*NMSS
*MIS System
*RIV Files (2)
*RSTS Operator

*w/766

8703020342 870220
REG. LIC30
35-00502-02 PDR

RIV: NMSS
LTRicketson
2/6/87

C: NMSS
RJEverett
2/9/87

C: R&SPB
WLFisher
2/11/87

D: DRSS
RLBangart
2/13/87

EO DP
DAPowers
2/18/87

B-10

IE-07

APPENDIX

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report: 30-05900/~~86-03~~ ⁸⁷⁻⁰¹ License: 35-00502-02
30-20094/~~86-02~~ ⁸⁷⁻⁰¹ 35-00502-05

Docket: 30-05900
30-20094

Licensee: Halliburton Company
1015 Bois D'Arc
Duncan, Oklahoma 73536

Conference Conducted: January 26, 1987

Report Prepared by:

Larry Ricketson, P.E. ²⁻⁶⁻⁸⁷
Larry Ricketson, P.E., Radiation Specialist Date

Approved:

R. J. Everett, Jr. ^{2/9/87}
R. J. Everett, Chief, Nuclear Materials Date
Safety Section

Conference Summary

Conference held on January 26, 1987 (Report 30-05900/~~86-03~~ ⁸⁷⁻⁰¹ and 30-20094/~~86-02~~ ⁸⁷⁻⁰¹)

An enforcement conference was held at the Region IV office in Arlington, Texas, to discuss the findings of the NRC inspection conducted December 8-12, 1986. The violations and issues of concern were detailed by the Region IV staff, and the licensee responded to each item.

Results: The NRC presented 12 apparent violations of NRC requirements and expressed concern regarding the management control of the licensed program. The licensee representatives responded relative to their understanding of the violations, acknowledged the findings, and presented no information that would allow deletion or modification of the violations. The licensee described the actions taken or planned to bring the licensed program within full compliance of NRC requirements. The NRC explained that a system of management controls should be implemented to ensure that full compliance would be maintained in the future. Consolidation of the licensee's activities under fewer licenses was discussed as a possible means to increase the efficiency of oversight operations. The NRC staff explained the enforcement policy and stated that a decision would be made as to the appropriate enforcement action and that the licensee would then be notified.

8703020354 870220
REC4 LIC30
35-00502-02 PDR

Persons Participating in the Conference

A. Licensee

James A. Dunlop, President, Halliburton Services
Ron Bechtel, Manager, Government Regulations
Richard A. Leonardi, Jr., Radiation Safety Officer
Ralph Houser, Senior Environment Engineer

B. NRC - Region IV

R. Bangart, Director, Division of Radiation Safety and Safeguards
W. Fisher, Chief, Radiological and Safeguards Programs Branch
J. Everett, Chief, Nuclear Materials Safety Section
D. Powers, Enforcement Officer
L. Ricketson, Radiation Specialist