



HALLIBURTON SERVICES

GOVERNMENT REGULATIONS DEPARTMENT

R. L. BECHTEL
Manager

R. A. LEONARDI JR.
Radiation Safety Officer

Writer's Direct Dial Number

(405) 251-3565

DRAWER 1431 DUNCAN OKLAHOMA 73536-0100

Senior Environmental Engineers

S. A. BURFORD
R. E. HOUSER

Environmental Engineers

J. W. PRESGROVE
J. R. SANDERS, JR.

RECEIVED

SEP 28 1987

September 23, 1987

Mr. Richard Bangart, Director
Division of Radiation Safety and
Safeguards
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Sir:

Halliburton Services is currently planning to ship to the U. S. Ecology, Beatty, Nevada disposal site the low level waste associated with the cleanup activities, performed under License No. 35-00502-03, relative to the rod rack cutting operation conducted at the North 40 facility on Osage Road. Analyses of soil samples taken at discrete points within the cleanup area indicate contamination levels are below those specified for unrestricted release in our letter of May 7, 1987. It is our intention to terminate cleanup activities and release the facility for unrestricted use.

Very truly yours,

R. L. Bechtel

R. L. Bechtel

RLB:im

cc: Mr. Bob Tiner
Mr. Richard Leonardi

8710020200 870923
REG 4 LIC 30
35-00502-05 PDR