

Appendix D

Procedure Listing

OPERATIONAL PROCEDURES

Procedure Number	Procedure Title	Procedure Number	Procedure Title
QAP	Quality Assurance Plan	RS-012.0	Respiratory Protection
QCP-001	Document Control	RS-013.0	Routine Operability of Field Instruments
QCP-002	Audits	RS-013.1	Calibration of the URSA II System
QCP-003	Calculations	RS-013.2	Calibration of Ludlum 2350-1
RSP-001	Radiation Safety Plan	RS-013.3	Calibration and Use of the Ludlum 2929 Alpha-Beta Detector
RS-002.0	Zoning and Posting Restricted Areas	RS-013.5	Calibration of Ludlum Gas-Flow Proportional Detectors
RS-003.0	Access Control for Restricted Areas	RS-013.6	Air Sampler Calibration
RS-004.0	Control and Storage	RS-014.0	Training and Qualification
RS-005.0	Radiation Work Permits	RS-016.0	Radiation Safety Incident Reports
RS-005.1	Radiation Safety Work Instructions and Work Plans	RS-018.0	Transportation
RS-006.0	Contamination Control	RS-020.0	Sample Chain of Custody
RS006.1	Decontamination of Equipment and Tools	RS-021.0	Surface Soil Sampling
RS-007.0	ALARA	RS-022.0	Subsurface Soil Sampling
RS-008.0	Air Monitoring	RS-023.0	Sample Handling
RS-009.0	External Dosimetry	RS-024.0	Air Sampler Calibration
RS-010.0	Surveys	RS-025.0	Sediment Sampling
RS-010.1	Scanning Surveys	RS-026.0	Liquid Discharges
RS-010.2	Static Surveys	RS-027.0	HEPA Filter Testing
RS-011.0	Protective Equipment	RS-028.0	Internal Dosimetry