



1801 Route 51
Jefferson Hills, PA 15025
888.325.8517

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

June 4, 2012

REPLY TO A NOTICE OF VIOLATION

Docket No.: 99901412
Violation 99901412/2012-201-01

Inspection Report No.: 99901412/2012-201

To Whom It May Concern:

Provided below please find our reply to the subject violation, summarized as follows:

As of March 23, 2012, Clark failed to adopt appropriate procedures in accordance with 10 CFR 21.21(a)(2) and 10 CFR 21.21(a)(3). Specifically, Clark's 10 CFR Part 21 implementing procedure, QAP 08.03.02 "Reporting of Defects and Noncompliances to the NRC," Revision 0 dated July 26, 2010 failed to include the following provisions:

- 1. Ensure that if an evaluation cannot be completed within 60 days from discovery of the deviation or failure to comply, an interim report is prepared and submitted to the Commission through a director or responsible officer or designated person within 60 days of discovery of the deviation or failure to comply.*
- 2. Ensure that a director or responsible officer is informed as soon as possible and, in all cases, within 5 working days after completion of the evaluation.*

Reason for the Violation

This was an oversight during the creation of the initial version of QAP 08.03.02.

Corrective Steps That Have Been Taken and the Results Achieved

Clark's QAP 08.03.02 has been modified (Revision 2 dated March 29, 2012) to specify the requirement for interim reporting through a responsible officer (the Clark QA Manager or designate) to the NRC in cases where the evaluation of the discovered deviation or failure to comply will take more than 60 days, and the requirement for internal reporting (to the Clark QA Manager or designate) as soon as possible and, in all cases, within 5 working days after completion of the evaluation. We also added an easy to follow flowchart of the reporting process. As a result, our 10 CFR Part 21 implementing procedure is now complete and more clear. Training was conducted for all appropriate employees on March 29 and April 4, 2012, and the revised procedure was posted in the shop.

Corrective Steps That Will Be Taken

All necessary corrective steps have been taken, as described above.

Date When Full Compliance Will Be Achieved

Full compliance was achieved as of April 4, 2012 as described above.

Please don't hesitate to contact me if you have any questions or need further information.

Sincerely,

Gary Felicetti
QA Manager
1801 Route 51
Pittsburgh, PA 15025
412.387.1017

IED 9
NRD



1801 Route 51
Jefferson Hills, PA 15025
888.325.8517

REPLY TO A NOTICE OF VIOLATION

Docket No.: 99901412
Violation 99901412/2012-201-01

Inspection Report No.: 99901412/2012-201

Cc: Chief, Mechanical Vendor Branch
Division of Construction Inspection and Operational Programs
Office of New Reactors
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001