



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001

July 11, 2012

Mr. Matthew W. Sunseri
President and Chief Executive Officer
Wolf Creek Nuclear Operating Corporation
Post Office Box 411
Burlington, KS 66839

SUBJECT: WOLF CREEK GENERATING STATION – CLOSEOUT OF BULLETIN 2011-01,
"MITIGATING STRATEGIES" (TAC NO. ME6501)

Dear Mr. Sunseri:

On May 11, 2011, the U.S. Nuclear Regulatory Commission (NRC) issued Bulletin 2011-01, "Mitigating Strategies" (Agencywide Documents Access and Management System (ADAMS) Accession No. ML111250360), to all holders of operating licenses for nuclear power reactors, except those that have permanently ceased operation and have certified that fuel has been removed from the reactor vessel. The purpose of NRC Bulletin 2011-01 (the bulletin) was to obtain a comprehensive verification that licensees' mitigating strategies to maintain or restore core cooling, spent fuel cooling, and containment following a large explosion or fire were compliant with Title 10 of the *Code of Federal Regulations* (10 CFR) paragraph 50.54(hh)(2).

The bulletin required two sets of responses pursuant to the provisions of 10 CFR 50.54(f). Wolf Creek Nuclear Operating Corporation, the licensee for Wolf Creek Generating Station, provided its responses to the bulletin by letters dated June 9 and July 11, 2011. Portions of the letter dated July 11, 2011, contain sensitive unclassified non-safeguards information and, accordingly, have been withheld from public disclosure. By letter dated November 30, 2011, the NRC sent a request for additional information (RAI) associated with the July 11, 2011, response. The licensee responded to the RAI by letter dated January 15, 2012.


The NRC staff has reviewed the information submitted by the licensee and concludes that its response to the bulletin is acceptable. The NRC staff summary of NRC Bulletin 2011-01 response review is enclosed. No further information or actions under the bulletin are requested.

M. Sunseri

- 2 -

Please feel free to contact me at (301) 415-3049 if you have any questions.

Sincerely,

A handwritten signature in black ink, appearing to read "Terry A. Beltz", with a long horizontal flourish extending to the right.

Terry A. Beltz, Senior Project Manager
Plant Licensing Branch IV
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-482

Enclosure:

As stated

cc w/encl: Distribution via Listserv

SUMMARY OF NRC BULLETIN 2011-01, "MITIGATING STRATEGIES" RESPONSE

REVIEW BY THE OFFICE OF NUCLEAR REACTOR REGULATION

WOLF CREEK NUCLEAR OPERATING CORPORATION

WOLF CREEK GENERATING STATION

DOCKET NO. 50-482

1.0 INTRODUCTION

On May 11, 2011, the U.S. Nuclear Regulatory Commission (NRC) issued Bulletin 2011-01, "Mitigating Strategies" (Agencywide Documents Access and Management System (ADAMS) Accession No. ML111250360), to all holders of operating licenses for nuclear power reactors, except those that have permanently ceased operation and have certified that fuel has been removed from the reactor vessel. Bulletin 2011-01 (the bulletin) required two sets of responses pursuant to the provisions of Title 10 of the *Code of Federal Regulations* (10 CFR) paragraph 50.54(f). The first response was due 30 days after issuance of the bulletin. By letter dated June 9, 2011 (ADAMS Accession Nos. ML11166A094), Wolf Creek Nuclear Operating Corporation, the licensee for Wolf Creek Generating Station, provided its response to the first set of questions (first response). The second response was due 60 days after issuance of the bulletin. By letter dated July 11, 2011 (ADAMS Accession No. ML11200A130), the licensee provided its response to this second set of questions (second response). Portions of the letter dated July 11, 2011, contain sensitive unclassified non-safeguards information and, accordingly, have been withheld from public disclosure. By letter dated November 30, 2011 (ADAMS Accession No. ML113220291), the NRC sent a request for additional information (RAI) on the second response. The licensee responded to the RAI by letter dated January 15, 2012 (ADAMS Accession No. ML12031A158). As summarized below, the NRC staff has verified that the licensee provided the information requested in the bulletin.

2.0 BACKGROUND

On February 25, 2002, the NRC issued EA-02-026, "Order for Interim Safeguards and Security Compensatory Measures" (ICM Order). Section B.5.b of the ICM Order required licensees to develop specific guidance and strategies to maintain or restore core cooling, containment, and spent fuel pool cooling capabilities using readily available resources (equipment and personnel) that can be effectively implemented under the circumstances associated with the loss of large areas of the plant due to explosions or fire.

By letter dated August 2, 2007 (ADAMS Accession No. ML072110517), the NRC staff issued its safety evaluation (SE) to document the final disposition of information submitted by the licensee regarding Section B.5.b of the ICM Order. Along with the SE, the staff issued a conforming license condition to incorporate the B.5.b mitigating strategies into the licensing basis.

On March 27, 2009, the NRC issued 10 CFR 50.54(hh)(2) as a new rule (74 FR 13926), in order to capture the B.5.b mitigating strategies and related license conditions as regulatory

Enclosure

requirements for both current and future licensees. At that time, licensee compliance with the conforming license conditions was sufficient to demonstrate compliance with 10 CFR 50.54(hh)(2), so no further actions were required on the part of current licensees.

3.0 TECHNICAL EVALUATION

3.1 30-Day Request

In order to confirm continued compliance with 10 CFR 50.54(hh)(2), the bulletin requested that licensees address the following two questions within 30 days of issuing the bulletin:

- Is the equipment necessary to execute the mitigating strategies, as described in your submittals to the NRC, available and capable of performing its intended function?
- Are the guidance and strategies implemented capable of being executed considering the current configuration of your facility and current staffing and skill levels of the staff?

The NRC staff reviewed the licensee's first response (i.e., letter dated June 9, 2011) to determine if it had adequately addressed these questions.

3.1.1 Question 1: Availability and Capability of Equipment

In its first response, the licensee confirmed that the equipment it needs to execute the 10 CFR 50.54(hh)(2) mitigating strategies is available and capable of performing its intended function. The NRC staff verified that this confirmation covered equipment need for each of the three phases of B.5.b mitigating strategies.

Based on the above, the NRC staff concludes that the licensee has adequately responded to Question 1.

3.1.2 Question 2: Capability to Execute Guidance and Strategies

In its first response, the licensee confirmed that the guidance and strategies it has implemented for 10 CFR 50.54(hh)(2) are capable of being executed considering the current facility configuration, staffing levels, and staffing skills.

Since the licensee has considered its current facility configuration, staffing levels, and staffing skills, and confirmed that it can execute its implement guidance and strategies, the NRC staff concludes that the licensee has adequately responded to Question 2.

3.2 60-Day Request

The bulletin required a response to the following five questions within 60 days of issuing the bulletin:

- Describe in detail the maintenance of equipment procured to support the strategies and guidance required by 10 CFR 50.54(hh)(2) in order to ensure that it is functional when needed.
- Describe in detail the testing of equipment procured to support the strategies and guidance required by 10 CFR 50.54(hh)(2) in order to ensure that it will function when needed.
- Describe in detail the controls for ensuring that the equipment is available when needed.
- Describe in detail how configuration and guidance management is ensured so that strategies remain feasible.
- Describe in detail how you ensure availability of offsite support.

The NRC staff reviewed the licensee's submittals to determine if it had adequately addressed these questions. This was accomplished by verifying that the submittals listed equipment, training, and offsite resources which were relied upon by NRC staff to make its conclusions in the SE dated August 2, 2007, or are commonly needed to implement the mitigating strategies.

3.2.1 Questions 1 and 2: Maintenance and Testing of Equipment

Questions 1 and 2 of the 60-day request required licensees to describe in detail the maintenance and testing of equipment procured to support the strategies and guidance required by 10 CFR 50.54(hh)(2) in order to ensure that it is functional when needed. In its second response, the licensee listed the equipment used to support the 10 CFR 50.54(hh)(2) mitigating strategies which receives maintenance or testing. For each item, the licensee described the maintenance and testing performed, including the frequency and basis for the maintenance or testing activity.

The NRC staff verified that the licensee listed equipment that typically requires maintenance or testing which was relied upon to make conclusions in the SE or commonly needed to implement the mitigating strategies. In its second response, the licensee stated that the portable pump (fire truck), hoses, and communications equipment receive maintenance or testing. The licensee did not identify maintenance or testing of monitor nozzles, spray nozzles, or similar devices in its second response. In its RAI response, the licensee described how it ensures that nozzles and similar devices will be functional when needed, and identified maintenance and testing of these devices that it plans to implement. In its RAI response, the licensee described in detail the semiannual maintenance of the portable pump and how sufficient fuel for the pump is ensured. The licensee also identified other items that support the mitigating strategies that receive maintenance or testing.

The NRC staff verified that the licensee described the process used for corrective actions and listed the testing performed to ensure that the strategies were initially feasible. The licensee stated in its second response that its 10 CFR Part 50, Appendix B, corrective action program is used to document equipment failure, establish priorities, and perform trending.

Based upon the above, the NRC staff concludes that the licensee has provided the information requested by Questions 1 and 2.

3.2.2 Question 3: Controls on Equipment

Question 3 of the 60-day request required licensees to describe in detail the controls on equipment, such as inventory requirements, to ensure that the equipment is available when needed. A list of inventory deficiencies and associated corrective actions to prevent loss was also requested.

The NRC staff verified that the licensee described its process for ensuring that B.5.b equipment will be available when needed. In its second response, the licensee identified equipment included in its inventory, the inventory frequency, storage requirements, and items verified. Items verified include proper quantity, locations, and accessibility of equipment and controls on storage locations. The licensee states that at the time of its second response there were no outstanding inventory deficiencies that would render the strategies not viable.

The NRC staff verified that the licensee inventoried equipment which was relied upon to make conclusions in the SE or commonly needed to implement the mitigating strategies. In its second response, the licensee stated that procured non-permanently installed B.5.b equipment is inventoried in accordance with station procedures. The second response specifically states that the following items are included in the inventory: portable pump, hoses, communications equipment, nozzles, connectors, and firefighter turnout gear. The NRC staff noted that tools and instruments were not listed in the second response. The second response also did not specify a minimum inventory frequency for B.5.b equipment which would cover equipment not specifically listed. In response to an RAI about this issue, the licensee described its inventory controls on tools and instruments used to implement the B.5.b mitigating strategies. The NRC staff noted that nearly all times listed were inventoried at least quarterly. The licensee also identified other items that support the mitigating strategies that are inventoried.

Based upon the above, the NRC staff concludes that the licensee has provided the information requested by Question 3.

3.2.3 Question 4: Configuration and Guidance Management

Question 4 of the 60-day request required licensees to describe in detail how configuration and guidance management is assured so that the strategies remain feasible.

The NRC staff verified that the licensee described its measures to evaluate plant configuration changes for their effects on the mitigating strategies and to ensure its procedures are current. In its second response, the licensee stated that plant configuration changes are procedurally evaluated against the licensing basis, which includes the B.5.b mitigating strategies. The licensee stated that the design change process requires a review of affected procedures and

that procedure changes are validated to ensure that the B.5.b mitigating strategies remain viable.

The NRC staff verified that the licensee described measures it has taken to validate the procedures or guidelines developed to support the mitigating strategies. In its second response, the licensee identified testing in response to Question 2 that demonstrated the ability to execute some strategies. The licensee also stated that "initially, mitigating strategies were validated by walk-through, engineering evaluations and/or table top reviews," and they were revalidated in 2011.

The NRC staff verified that the licensee described the training program implemented in support of the mitigating strategies and how its effectiveness is evaluated. In its second response, the licensee identified the training provided to its operations personnel, emergency response organization, including key decision makers, security personnel, and fire brigade. The licensee also identified the frequency with which each type of training is provided and the methods for training evaluating.

Based upon the above, the NRC staff concludes that the licensee has provided the information requested by Question 4.

3.2.4 Question 5: Offsite Support

Question 5 of the 60-day request required licensees to describe in detail how offsite support availability is assured.

The NRC staff verified that the licensee listed the offsite organizations it relies upon for emergency response, including a description of agreements and related training. The NRC staff compared the list of offsite organizations that the licensee provided in its second response with the information relied upon to make conclusions in the SE. The licensee stated that it maintains letters of agreement with these organizations, and that these agreements were current at the time of its second response. The letters of agreement are validated on a biennial basis. The licensee also described the training and site familiarization it provides to these offsite organizations. The licensee stated that it reviewed its corrective action program back to 2008 and found no issues involving lapsed agreements related to offsite support for B.5.b events.

Based upon the above, the NRC staff concludes that the licensee has provided the information requested by Question 5.

4.0 CONCLUSION

As described above, the NRC staff verified that the licensee has provided the information requested in Bulletin 2011-01. Specifically, the licensee responded to each of the questions in the bulletin as requested. The NRC staff concludes that the licensee has completed all of the requirements of the bulletin and that no further information or actions under the bulletin are needed.

M. Sunseri

- 2 -

Please feel free to contact me at (301) 415-3049 if you have any questions.

Sincerely,

/RA/

Terry A. Beltz, Senior Project Manager
Plant Licensing Branch IV
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-482

Enclosure:

As stated

cc w/encl: Distribution via Listserv

DISTRIBUTION:

PUBLIC

LPLIV Reading

RidsAcrsAcnw_MailCTR Resource

RidsNrrDorIDpr

RidsNrrDorILpl4 Resource

RidsNrrLAJBurkhardt Resource

RidsNrrPMWolfCreek Resource

RidsOgcRp Resource

RidsRgn4MailCenter Resource

BPurnell, NRR/DPR/PGCB

ADAMS Accession No. ML12191A154

*via memorandum

OFFICE	NRR/LPL4/PM	NRR/LPL4/LA	NRR/DPR/PGCB/BC (A)	NRR/LPL4/BC	NRR/LPL4/PM
NAME	TBeltz	JBurkhardt	KMorgan-Butler*	MMarkley	TBeltz
DATE	7/10/12	7/10/12	6/28/12	7/11/12	7/11/12

OFFICIAL RECORD COPY