

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Janx Integrity Group
5712 East Dallas Drive
Terre Haute, Indiana

REPORT NUMBER(S) 12-003

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-11772

4. LICENSE NUMBER(S)

21-16560-01

5. DATE(S) OF INSPECTION

6/14/2012

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.



Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Bill C. Lin		7/2/12
BRANCH CHIEF	Hironori Peterson		7/9/12

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Janx Integrity Group 5712 East Dallas Drive Terre Haute, Indiana REPORT NUMBER(S) 12-003		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-11772	4. LICENSE NUMBER(S) 21-16560-01	5. DATE(S) OF INSPECTION 6/14/2012	
6. INSPECTION PROCEDURES USED 87121	7. INSPECTION FOCUS AREAS FE1-FE7		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT William Reeves, RSO	4. TELEPHONE NUMBER (517) 531-8210
---------------------------------	----------------------	--	---

- ☐ Main Office Inspection Next Inspection Date: 06/2013
- ☒ Field Office Inspection 5712 East Dallas Drive, Terre Haute, Indiana
- ☒ Temporary Job Site Inspection Evansville, Indiana

PROGRAM SCOPE

The licensee is a radiography company with the corporate office located in Parma, Michigan. The licensee has numerous field stations within NRC and Agreement States jurisdictions. The corporate radiation safety officer (RSO) is located in the Parma, Michigan office and he reports directly to the Safety Director. Currently, the radiographers for 5712 East Dallas Drive are operating out of their residence. Records generated by the radiographers at the Terre Haute location are mailed to the licensee's corporate office each week.

Performance Observation

The inspector observed two qualified radiographers perform three radiography exposures using an iridium-192 camera. The operations were performed in accordance with all applicable regulatory requirements. The radiographers were knowledgeable of all safety requirements and procedures. The inspector observed that the radiographers had all of the applicable dosimetry, survey instruments, and emergency operating procedures prior to performing the exposures. The radiographers performed all of the required surveys associated with performing industrial radiography.

The inspector was unable to review the radiation safety records at the time of the inspection. All of the radiation safety records are located at the licensee's corporate office in Parma, Michigan. However during the inspection, the inspector held a conference call with the corporate RSO and discussed information such as the radiographers' dosimetry records, radiation safety training, and field audits. All of the information provided by the licensee's RSO was in accordance with NRC regulatory requirements. The radiation safety records located at the licensee's corporate office will be reviewed during an NRC inspection at that facility.

No violations of NRC requirements were identified.

