

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

Midwest Family Practice, PLC  
30801 Schoenherr Road  
Warren, MI 48093

REPORT NUMBER(S) 12-01

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-38494

4. LICENSE NUMBER(S)

21-32836-01

5. DATE(S) OF INSPECTION

July 19, 2012

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.



Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Aaron T. McCraw		7/30/12
BRANCH CHIEF	Tamara E. Bloomer		7/30/12

*Docket File Information*

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  Midwest Family Practice, PLC 30801 Schoenherr Road Warren, MI 48093  REPORT NUMBER(S) 12-01		2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S)  030-38494	4. LICENSE NUMBER(S)  21-32836-01	5. DATE(S) OF INSPECTION  July 19, 2012	
6. INSPECTION PROCEDURES USED  IP 87130	7. INSPECTION FOCUS AREAS  03.01-03.07		

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)  02121	2. PRIORITY  5	3. LICENSEE CONTACT  Sam Awada, MD	4. TELEPHONE NUMBER  (734) 395-7361
---------------------------------	----------------------	--	---

- ☒ Main Office Inspection      Next Inspection Date:      07/19/2017
- ☐ Field Office Inspection
- ☐ Temporary Job Site Inspection

**PROGRAM SCOPE**

This was an initial inspection of a medical clinic that offers cardiac imaging services. The licensee was authorized to use materials permitted by 10 CFR 35.100 and 35.200. The licensee employed one nuclear medicine technologist with 22 years of experience in the field of diagnostic imaging. The licensee scanned, on average, four cardiac patients per day, both resting and stress studies. The licensee conducted studies Monday through Friday. The licensee used only unit doses received from a local radiopharmacy. The licensee retained the services of a consulting physicist who reviews the program quarterly. The licensee had been conducting principal activities for approximately 1.5 months at the time of the inspection.

**PERFORMANCE OBSERVATIONS**

During this inspection, the inspector interviewed licensee personnel; observed one patient injection; performed independent surveys; and reviewed select records. The inspector reviewed dose calibrator records, package receipt records, training records, and waste disposal records. The licensee demonstrated the daily dose calibrator checks. The inspector observed appropriate dosimetry being worn by the nuclear medicine technologist and stress technician. The licensee had not been operating long enough for a badge exchange; therefore, the inspector could not review or record typical doses for this facility. The licensee possessed a calibrated and operable survey instrument that performed comparably to the inspector's survey instrument. The nuclear medicine technologist was knowledgeable of daily preparatory activities, operating procedures, spill procedures, and end-of-day activities.

No violations were identified during this inspection.