



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
1600 EAST LAMAR BLVD  
ARLINGTON, TEXAS 76011-4511

August 9, 2012

EA-12-098

Thomas G. Becnel  
Statoil USA E&P, Inc.  
2103 City West Blvd. Suite 800  
Houston, Texas 77042

SUBJECT: EXERCISE OF ENFORCEMENT DISCRETION

Dear Mr. Becnel:

This letter refers to your letter dated July 24, 2012 (ML12208A127), which you sent in response to our correspondence dated June 28, 2012, which the NRC sent regarding the circumstances surrounding the transfer of a fixed gauging device from Roxar, Inc., to Statoil USA E&P, Inc. (Statoil USA), in 2009. At the time of the transfer, an NRC license was required for possession and use of the device. However, at present, the fixed gauging device possessed by Statoil USA can be possessed, with the appropriate labeling and documentation, as a generally licensed device. It is our understanding that Roxar, Inc., has provided you with instructions for meeting the NRC general license requirements, you have completed or committed to complete the actions required to comply with the NRC general license requirements, and you have committed to installing the required labels the first time the device is returned to the surface. Labels are not required if the device is being decommissioned when returned to the surface.

Based on the above information, the NRC has determined that a violation of NRC requirements occurred. The violation involved possession and use of byproduct material without a specific NRC license in accordance with 10 CFR 30.3, Activities requiring license. Specifically, from 2009 to January 12, 2012, Statoil USA possessed a fixed gauging device containing byproduct material (a sealed source containing 30 millicuries of cesium-137) and did not hold a specific NRC license for the device. Although the device now meets NRC general license requirements, for the period of the violation it was not considered a generally licensed device, and a specific NRC license was required.

The violation was evaluated in accordance with the NRC Enforcement Policy. The current Enforcement Policy is on the NRC's Web site at <http://www.nrc.gov/about-nrc/regulatory/enforcement/enforce-pol.html>. A violation of 10 CFR 30.3 is normally categorized at Severity Level IV. However: (1) the failure to obtain an NRC license did not result in an actual safety, health, or security consequence, (2) the failure was not willful, (3) at the time of installation, Roxar, Inc., presented the position that it would handle all regulatory requirements associated with possession and use of the gauge even though this was counter to the NRC regulations, (4) the device will be registered in the NRC's General Licensee Tracking System, (5) you have committed to adhere to all requirements of your general license, and (6) you have committed to install the appropriate general license label on the device the first time that the

device is returned to the surface. Therefore, in accordance with the NRC Enforcement Policy, the NRC is exercising enforcement discretion to not issue a violation.

No further action or response is necessary on your part. You are not required to respond to this letter unless the description herein does not accurately reflect your corrective actions or your position.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and your response, should you choose to provide one, will be available electronically for public inspection in the NRC Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Should you have any questions concerning this letter, please contact Mr. Jason Razo at 817-200-1589 or Mr. Michael Vasquez at 817-200-1130.

Sincerely,

***/RA/ by VHCampbell for***

Anton Vogel, Director  
Division of Nuclear Materials Safety

Docket: 9999-0004  
General Licensee

cc:  
Richard A. Ratliff, P.E., L.M.P., Chief  
Radiation Safety Licensing Branch Manager  
Division for Regulatory Services  
TX Dept. of State Health Services  
P.O. Box 149347 Mail Code 2835  
Austin, TX 78714-9347

Roxar Flow Measurement, Inc.  
ATTN: Ms. Marie Benson  
6005 Rogerdale Road  
Mail Stop: SC200.2  
Houston, Texas 77072

Statoil USA E&P Inc.  
EA-12-098

- 3 -

Internal distribution:

E. Collins, RA  
A. Vogel, D:DNMS  
V. Campbell, DD:DNMS  
H. Gepford, C:ACES  
J. Whitten, C:NMSB-B  
M. Vasquez, C:NMSB-A  
R. Browder, SES:ACES  
C. Maier, ES:ACES  
R. Erickson, ASLO  
B. Maier, RSLO  
R. Zimmerman, D:OE  
N. Hilton, C:EB  
R4DNMS\_MS-A  
M. Herrera, Fee Coordinator

Hard copy:

RIV Materials Docket File

S:\DNMS\~ESCALATED ENFORCEMENT\ACTIVE CASES\Roxar\customer enforcement\final  
action letters\Statoil Discretion EA-12-098.docx ML12223A061

ADAMS		<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input checked="" type="checkbox"/> SUNSI Review Complete	Reviewer Initials: JMR
<input checked="" type="checkbox"/> Publicly Available		<input type="checkbox"/> Non-publicly Available		<input type="checkbox"/> Sensitive	<input checked="" type="checkbox"/> Non-sensitive
RIV:DNMS/NMSB-A	C:NMSB-A	C:ACES	D:DNMS		
JMRazo;dlf	GMVasquez	HJGepford	AVegel		
/RA/	<b>JEWhitten for</b>	<b>MCMaier for</b>	<b>VHCampbell for</b>		
8/1/12	8/2/12	8/8/12	8/9/12		

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax