



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION**  
REGION II  
245 PEACHTREE CENTER AVENUE NE, SUITE 1200  
ATLANTA, GEORGIA 30303-1257

August 21, 2012

Mr. Larry Smith  
Plant Manager  
Honeywell Metropolis Works  
P.O. Box 430  
Metropolis, IL 62960

SUBJECT: HONEYWELL METROPOLIS WORKS: INVESTIGATIVE SYNOPSIS, OFFICE  
OF INVESTIGATIONS CASE NUMBER 2-2012-004

Dear Mr. Smith:

Enclosed for your information is the synopsis of the Nuclear Regulatory Commission (NRC) Office of Investigations' (OI) completed report regarding a concern that a licensee employee (unidentified) willfully caused a contaminated tool to be removed from the Honeywell Metropolis Works site in Metropolis, IL without the required surveys.

OI determined that based on the documentation and testimony developed, the investigation did not substantiate the allegation that a licensee employee caused a contaminated tool to be removed from Honeywell without the required surveys.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/NRC/ADAMS/index.html> (the Public Electronic Reading Room).

Sincerely,

**/RA/**

Joselito O. Calle, Chief  
Fuel Facility Inspection Branch 2  
Division of Fuel Facility Inspection

Docket No. 40-3392  
License No. SUB-526

Enclosure: Investigative Synopsis,  
OI Case No. 2-2012-004

cc w/encl: Oscar de Miranda

August 21, 2012

Mr. Larry Smith  
Plant Manager  
Honeywell Metropolis Works  
P.O. Box 430  
Metropolis, IL 62960

SUBJECT: HONEYWELL METROPOLIS WORKS: INVESTIGATIVE SYNOPSIS, OFFICE  
OF INVESTIGATIONS CASE NUMBER 2-2012-004

Dear Mr. Smith:

Enclosed for your information is the synopsis of the Nuclear Regulatory Commission (NRC) Office of Investigations' (OI) completed report regarding a concern that a licensee employee (unidentified) willfully caused a contaminated tool to be removed from the Honeywell Metropolis Works site in Metropolis, IL without the required surveys.

OI determined that based on the documentation and testimony developed, the investigation did not substantiate the allegation that a licensee employee caused a contaminated tool to be removed from Honeywell without the required surveys.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/NRC/ADAMS/index.html> (the Public Electronic Reading Room).

Sincerely,  
/RA/

Joselito O. Calle, Chief  
Fuel Facility Inspection Branch 2  
Division of Fuel Facility Inspection

Docket No. 40-3392  
License No. SUB-526

Enclosure: Investigative Synopsis,  
OI Case No. 2-2012-004

cc w/encl: Oscar de Miranda

\*see previous concurrence

X PUBLICLY AVAILABLE

☐ NON-PUBLICLY AVAILABLE

☐ SENSITIVE

X NON-SENSITIVE

ADAMS: X Yes

ACCESSION NUMBER: ML12234A566

X SUNSI REVIEW COMPLETE X FORM 665 ATTACHED

OFFICE	RII:DFFI	RII:EICS					
SIGNATURE	/RA/	CFE for					
NAME	RGibson*	ODeMiranda*					
DATE	8/ 20 /12	8/ 20 /12	8/ /2012	8/ /2012	8/ /2012	8/ /2012	8/ /2012
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY  
HONEYWELL.DOCX

DOCUMENT NAME: G:\DFFI\BRANCH 2\HONEYWELL\RII-2011-A-0180 LTR SYNOPSIS

~~Official Use Only – OI Investigation Information~~

SYNOPSIS

This investigation was initiated by the U.S. Nuclear Regulatory Commission (NRC), Office of Investigations (OI), Region II (RII), on October 19, 2011, to determine whether a licensee employee (unidentified) willfully caused a contaminated tool to be removed from Honeywell International, Inc. (Honeywell) site without the required surveys.

Based upon the documentation and testimony developed during this investigation, OI:RII did not substantiate that a licensee employee willfully caused a contaminated tool to be removed from Honeywell without the required surveys.

Approved for release  
By Oscar DeMiranda

~~NOT FOR PUBLIC DISCLOSURE WITHOUT APPROVAL OF  
SPECIAL AGENT IN CHARGE, OFFICE OF INVESTIGATIONS, REGION II~~

~~Official Use Only – OI Investigation Information~~