



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
1600 EAST LAMAR BLVD
ARLINGTON, TEXAS 76011-4511

FEBRUARY 22, 2013

MEMORANDUM TO: Robert Sun, Health Physicist (T-8E24)
Radioactive Materials Safety Branch
Division of Materials Safety & State Agreements

FROM: G. Michael Vasquez, Chief */RA ADGaines/ for*
Nuclear Materials Safety Branch A
Division of Nuclear Materials Safety

SUBJECT: MATERIALS LICENSEE EVENT REPORT SUMMARY

Enclosed is the subject report for February, 2013. This enclosure documents the licensee event reports that were closed in December 2012 and January 2013 and lists ADAMS ML numbers for documents associated with these events, detailing Region IV's response.

Enclosure:
February 2013 RIV DNMS Licensee
Event Reports Summary Table

cc via email w/Enclosure

E. Collins

A. Vogel

V. Campbell

J. Whitten

D. Spitzberg

J. Thompson

D. Huntsman [Dante.Huntsman@inl.gov]

Hard Coy

LER File

S:\DNMS\INMIB\LERs\2012\12-2012 & 1- 2013.doc

ADAMS	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> SUNSI Review Complete	Reviewer Initials: JLT
	<input checked="" type="checkbox"/> Publicly Available	<input checked="" type="checkbox"/> Non-sensitive		
	<input type="checkbox"/> Non-publicly Available	<input type="checkbox"/> Sensitive		
KEYWORD: SUNSI Review Complete				
RIV:DNMS/NMSB-A			C:NMSB-A	
JLThompson			GMVasquez	
/RA/			/RA ADGaines/ for	

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - FEBRUARY 2013								
ADAMS ML # or Event #	Event Date	Notification Date	Licensee	License Number	Reporting Requirement	Event Description	Assigned Inspector	Review Status
47309	9/30/2011	10/3/2011	United States Air Force	42-23539-01AF	10 CFR 20.2201	Lost americium-241 sealed source (12 millicuries)	Cook	Open
48193	8/15/2012	8/15/2012	United States Air Force	42-23539-01AF	10 CFR 20.2201	Lost americium-241 sealed source (0.25 millicuries) in a CAD	Cook	Open
47996	6/5/2012	6/5/2012	Inberg-Miller Engineers	49-19477-01	10 CFR 30.50	Troxler portable nuclear gauge was damaged at a temporary jobsite when run over in Cheyenne, Wyoming	Munoz	Open
48532	11/22/2012	11/23/2012	Bayou Inspection Services	LA-7112-L01	10 CFR 30.50	Radiography source disconnect on pipe lay barge in offshore Federal waters near Louisiana	Stearns	Open
48516	11/16/2012	11/17/2012	Acuren USA	42-32443-01	10 CFR 30.50	Radiography source disconnect on the north slope of Alaska	Razo	Open
ML13015A182	12/9/2012	1/3/2013	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment, cesium-137 and Am-241 source	Thompson	Closed
ML13036A574	1/11/2013	2/5/2013	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment, cesium-137 and Am-241 source	Poston	Closed
ML13036A552	12/25/2012	1/16/2013	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment, cesium-137 density source	Poston	Closed