



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
1600 EAST LAMAR BLVD  
ARLINGTON, TEXAS 76011-4511

March 4, 2013

Matthew Sunseri, President and  
Chief Executive Officer  
Wolf Creek Nuclear Operating Corporation  
P.O. Box 411  
Burlington, KS 66839

Subject: ERRATA FOR WOLF CREEK GENERATING STATION – NRC INTEGRATED  
INSPECTION REPORT 05000482/2012002

Dear Mr. Sunseri:

Please remove the page nine from the Wolf Creek Generating Station - NRC Integrated Inspection Report 05000482/2012002 and replace it with the page enclosed with this letter. The purpose of this change is to add documentation for an inspection sample completed during the report period.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response, if you choose to provide one for cases where a response is not required, will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>. To the extent possible, your response should not include any personal privacy or proprietary, information so that it can be made available to the Public without redaction.

Sincerely,

/RA/

Neil O'Keefe  
Chief, Project Branch B  
Division of Reactor Projects

Docket No. 50-482  
License No. NPF-42

Enclosure:  
NRC Inspection Report 05000482/2012002 ERRATA, Page 9

Distribution via Listserv

Electronic Distribution by RIV:

Regional Administrator (Elmo.Collins@nrc.gov)

Acting Deputy Regional Administrator (Steven.Reynolds@nrc.gov)

DRP Director (Kriss.Kennedy@nrc.gov)

Acting DRP Deputy Director (Michael.Scott@nrc.gov)

Acting DRS Director (Thomas.Blount@nrc.gov)

Acting DRS Deputy Director (Jeff.Clark@nrc.gov)

Resident Inspector (Charles.Peabody@nrc.gov)

Senior Project Engineer (Michael.Bloodgood@nrc.gov)

Project Engineer (David.You@nrc.gov)

Public Affairs Officer (Victor.Dricks@nrc.gov)

Public Affairs Officer (Lara.Uselding@nrc.gov)

Regional State Liaison Officer (Bill.Maier@nrc.gov)

Congressional Affairs Officer (Jenny.Weil@nrc.gov)

NRR Project Manager (Fred.Lyon@nrc.gov)

RITS Coordinator (Marisa.Herrera@nrc.gov)

TSB Technical Assistant (Loretta.Williams@nrc.gov)

ROPreports@nrc.gov

RIV/ETA: OEDO (John.Cassidy@nrc.gov)

R:\\_Reactors\2012\WC\Errata WC2012-002 rpt MRB.docx

SUNSI Rev Compl.	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	ADAMS	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Reviewer Initials	MRB
Publicly Available	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Sensitive	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sens. Type Initials	MRB
SPE:DRP/B	RI:DRP/B	C:DRP/B			
MBloodgood	CPeabody	NOKeefe			
/RA/	/RA/	/RA/			
2/28/2013	2/28/2013	3/4/2013			

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

b. Findings

No findings were identified.

**1R11 Licensed Operator Requalification Program and Performance (71111.11)**

.1 Quarterly Licensed Operator Requalification Program

a. Inspection Scope

On March 21, 2012, the inspectors observed a crew of licensed operators in the plant's simulator to verify that operator performance was adequate, evaluators were identifying and documenting crew performance problems; and training was being conducted in accordance with licensee procedures. The inspectors evaluated the following areas:

- Licensed operator performance
- Crew's clarity and formality of communications
- Crew's ability to take timely actions in the conservative direction
- Crew's prioritization, interpretation, and verification of annunciator alarms
- Crew's correct use and implementation of abnormal and emergency procedures
- Control board manipulations
- Oversight and direction from supervisors
- Crew's ability to identify and implement appropriate technical specification actions and emergency plan actions and notifications

These activities constitute completion of one quarterly licensed-operator requalification program sample as defined in Inspection Procedure 71111.11.

b. Findings

No findings were identified.

.2 Quarterly Observation of Licensed Operator Performance

The inspectors observed the response to the January 13, 2012 loss of offsite power event. The details of this inspection can be found in section 4OA3.3 of this report.

These activities constitute completion of one quarterly licensed-operator performance program sample as defined in Inspection Procedure 71111.11.

**1R13 Maintenance Risk Assessments and Emergent Work Control (71111.13)**

a. Inspection Scope

The inspectors reviewed licensee personnel's evaluation and management of plant risk for the maintenance and emergent work activities affecting risk-significant and safety-