



MAR 1 2013

ASME Code Case N-532-4

LR-N13-0040

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-001

Salem Nuclear Generating Station Unit 2
Renewed Facility Operating License No. DPR-75
NRC Docket No. 50-311

Subject: In-Service Inspection Activities – 90-Day Report, Revision 1

Reference: LR-N13-0021, In-Service Inspection Activities – 90 Day Report

PSEG Nuclear LLC submitted letter LR-N13-0021 dated February 1, 2013, to transmit to the NRC the Owner's Activity Report for In-Service Inspection (ISI) activities conducted at Salem Generating Station Unit 2 during the nineteenth refueling outage. Letter LR-N13-0021 included a typographical error in the Certificate of Conformance section of Enclosure 1. This letter corrects ADAMS Accession Nos. ML13038A231 and ML13039A335 and transmits the corrected report.

Enclosure 1 to this letter contains the Salem Unit 2 Owner's Activity Report, Revision 1. There are no commitments contained in this letter.

Should you have any questions regarding this submittal, please contact C.M. Dahms at (856) 339-5456.

Sincerely,

A handwritten signature in black ink, appearing to read "C. Fricker", written over a horizontal line.

Carl J. Fricker
Site Vice President - Salem
Enclosures (1)

MAR 1 2013

Document Control Desk

Page 2

LR-N13-0040

- C Mr. W. Dean, Administrator, Region I, NRC
 Mr. J. Hughey, Project Manager, NRC
 Ms. E. Bonney, NRC Senior Resident Inspector, Salem
 Mr. P. Mulligan, Manager IV, NJBNE
 Mr. L. Marabella, Corporate Commitment Tracking Coordinator
 Mr. T. Cachaza, Salem Commitment Tracking Coordinator
 Mr. Milton Washington, Chief Inspector – Occupational Safety and Health Bureau
 of Boiler and Pressure Vessel Compliance

Document Control Desk
Enclosure 1
LR-N13-0040

Salem Unit 2
Owners Activity Report – S2R19, Revision 1
In Accordance With ASME
Section XI Code Case N-532-4


FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number **S2RFO19 - Revision 1**
Owner **PSEG Nuclear LLC, PO Box 236, Hancocks Bridge, NJ 08038**
Plant **Salem Generating Station** Unit No. **2**
Commercial
Service Date **Oct. 13, 1981** Refueling Outage No. **19**
Current Inspection Interval **ISI - Third (3rd) {Containment IWE/IWL - Second (2nd)}**
Current Inspection Period **ISI - Third (3rd) {Containment IWE/IWL - First (1st)}**
Edition and Addenda of Section XI Applicable to the inspection plan **ISI - 1998 Edition - 2000 Addenda
CISI - (IWE/IWL) - 2004 Edition**
Date and revision of inspection plan **ISI - July 2012, Revision 2 {CISI - October 2010, Revision 0}**
Code Cases used **N-460, N-498-4, N-532-4, N-533-1, N-706, N-722-1 and N-731**

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of S2RFO19 conform to the requirements of Section XI.

Signed



Edley T. Giles / ISI Program Manager

Owner or Owner's Designee, Title


2/25/2013
Date

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of New Jersey and employed by Hartford Steam Boiler Inspection and Insurance Company of Connecticut have inspected the items described in this Owner's Activity Report, during the period May 8, 2011 to November 8, 2012, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Ross Goodwin



Inspector's Signature

Commissions NB 14086 A,N,I NJ955

National Board, State, Province, and Endorsements

Date

2/25/2013

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 1
ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED
EVALUATION FOR CONTINUED SERVICE

Exam Category	Item Number	Item Description	Evaluation Description
N/A	N/A	None	N/A

TABLE 2
ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR
CONTINUED SERVICE

Code Class	Item Description	Description of Work	Date Completed	Repair/ Replacement Plan Number
3	3/8" tubing leak downstream 22SW234	Replaced 3/8" SS tubing and fittings	07/11/2012	60104374
3	3/8" tubing leak downstream of 22SW235	Replaced 3/8" SS tubing	09/18/2012	60105576
3	1" weld leak upstream of 2SW310 on 90° elbow to flange butt weld	1" AL6XN elbow to flange butt weld excavated and re-welded	08/30/2012	60105108
3	3/8" tubing leak downstream of 2SW186	Replaced 3/8" SS tubing and fittings	11/14/2012	60106944
2	3/8" tubing to tee weld leak downstream of 2RC3	Replaced 3/8" SS tubing and fittings	11/14/2012	60106394
2	3/8" tubing leak downstream of 22BF24	Replaced 3/8" SS tubing and fittings	11/20/2012	60107143