



Note: C01 is Source 49; C02 is Source 50.

Progress Energy Carolinas
**Shearon Harris Nuclear Power Plant
Units 2 and 3**
Part 2, Final Safety Analysis Report
New Hill, North Carolina

Mean Hazard Curves for the
Rondout Associates Team Sources

FIGURE 2.5.2-225