

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9108150297 DOC. DATE: 91/08/14 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern Californ 05000362

AUTH. NAME AUTHOR AFFILIATION
 ROSENBLUM, R.M. Southern California Edison Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Advises that licensee will resubmit Relief Request B-7
 correcting errors & provide clear statement of relief
 requested for insps to be performed during upcoming Unit 2
 refueling outage & basis for relief by 910909.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 0	PD5 PD	1 1
	KOKAJKO, L.	2 2		
INTERNAL:	ACRS	6 6	AEOD/DSP/TPAB	1 1
	NRR/DET/ECMB 9H	1 1	NRR/DET/EMEB 7E	1 1
	NUDOCS-ABSTRACT	1 1	OC/LFMB	1 0
	OGC/HDS3	1 0	REG. FILE 101	1 1
	RES/DSIR/EIB	1 1		
EXTERNAL:	EG&G BROWN, B	1 1	EG&G RANSOME, C	1 1
	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 19

R
I
D
S
/
A
D
D
S
/
A
D
D
S

MA
8/1



Southern California Edison Company

23 PARKER STREET
IRVINE, CALIFORNIA 92718

August 14, 1991

R. M. ROSENBLUM
MANAGER OF
NUCLEAR REGULATORY AFFAIRS

TELEPHONE
(714) 454-4505

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Subject: Docket Nos. 50-361, and 50-362
First Ten-Year Interval Inservice Inspection
Program
San Onofre Nuclear Generating Station, Units 2
and 3 (TAC Nos. 54148 and 54149)

Reference: June 26, 1991 letter from Mr. R. M. Rosenblum to
Document Control Desk (NRC), Subject: Docket Nos.
50-361, and 50-362, First Ten-Year Interval
Inservice Inspection Program, San Onofre Nuclear
Generating Station, Units 2 and 3 (TAC Nos. 54148
and 54149)

Gentlemen:

As discussed on August 5, 1991 in a telephone call with Mr. L. E. Kokajko, NRC Project Manager for San Onofre Units 2 and 3, our inservice inspection letter of June 26, 1991 contains incorrect information concerning Relief Request B-7. This information may result in some confusion concerning the basis for the exemption requested by Relief Request B-7.

Specifically, for example, the June 26, 1991 letter mistakenly utilized a value of 3,500 as the number of welds subject to the Relief Request. Although the total number of welds in both units for the three categories B-J, B-F, and C-F is approximately 3,500, a lesser number require surface preparation for the code inspection to be performed.

9108150297 910814
PDR ADOCK 05000361
Q PDR

A047
110

We will resubmit Relief Request B-7 correcting any errors and provide a clear statement of the relief requested for inspections to be performed during the upcoming Unit 2 refueling outage and the basis for the relief by September 9, 1991.

Very truly yours,

A handwritten signature in cursive script, appearing to read "R. R. Baecker".

cc: J. B. Martin, Regional Administrator, NRC Region V
C. Caldwell, NRC Senior Resident Inspector, San Onofre Units
1, 2, 3