

Central File


Southern California Edison Company



P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

K. P. BASKIN
MANAGER, NUCLEAR ENGINEERING
AND LICENSING

March 4, 1980



TELEPHONE
(213) 572-1401

U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94596

Docket Nos. 50-361, 1362

Attention: Mr. R. H. Engelken, Director

Gentlemen:

Subject: NRC IE Bulletin 79-13 Revision 2,
Cracking in Feedwater System Piping
San Onofre Nuclear Generating Station, Units 2 and 3

In a letter to your office dated January 18, 1980 concerning NRC IE Bulletin No. 79-13, Revision 2, SCE proposed to utilize ultrasonic examination techniques supplemented as necessary by radiographic examination for reportable indications as an alternative to the radiographic examinations required by NRC IE Bulletin No. 79-13, Revision 2. SCE has evaluated this matter further and hereby withdraws our proposal to utilize alternative examination methods. SCE will implement an inspection program in accordance with the requirements of NRC IE Bulletin No. 79-13, Revision 2 and your letter of November 14, 1979.

Should you have any questions or require additional clarification please contact me.

Very truly yours,

K P Baskin

cc: U. S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

R. J. Pate (NRC, San Onofre Units 2 and 3)

8007230011

Q

RO/I
2

61