

Central
files

Southern California Edison Company

SCE

P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

K. P. BASKIN
MANAGER OF NUCLEAR ENGINEERING,
SAFETY, AND LICENSING

TELEPHONE
(213) 572-1401

January 5, 1981

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1990 North California Boulevard
Suite 202, Walnut Creek Plaza
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Gentlemen:

Subject: IE Bulletin 80-21
Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station
Units 2 and 3



Your letter of November 6, 1980 forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Company, Inc.," requests information regarding extent of use of this equipment in safety related systems at San Onofre Units 2 and 3 and requires that certain actions be taken if the faulty yokes are utilized.

SCE has contacted both the A/E (Bechtel) and the NSSS supplier (CE) regarding use of this equipment and information indicates that the suspect yokes are not used in safety related systems at S023. However, final written confirmation from Bechtel subvendors is still outstanding at this time. Should that information reveal that the suspect yokes are utilized, SCE will forward a second letter indicating so and outlining the corrective actions to be taken.


Should you have any questions or require additional clarification, please contact me.

Very truly yours,

KP Baskin

cc: NRC Office of Inspection
and Enforcement
Division of Reactor Construction Inspection
Washington, D.C. 20555

R. Pate, USNRC Site
Inspector, S0 2/3



A02

8101270 517

81-01