

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8903300373 DOC.DATE: 89/03/13 NOTARIZED: NO DOCKET #  
 FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361  
 50-362 San Onofre Nuclear Station, Unit 3, Southern Californ 05000362  
 AUTH.NAME AUTHOR AFFILIATION  
 MORGAN,H.E. Southern California Edison Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 MARTIN,J.B. Region 5, Ofc of the Director

SUBJECT: RO:follow-up rept of inoperable fire doors for Feb 1989.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3  
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1	PD5 PD	1 1
	HICKMAN,D	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	IRM/DCTS/DAB	1 1
	NRR/DEST/ADE 8H	1 1	NRR/DEST/ADS 7E	1 0
	NRR/DEST/CEB 8H	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/QAB 10	1 1
	NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
	NRR/DRIS/SIB 9A	1 1	NUDOCS-ABSTRACT	1 1
	<u>REG FILE 02</u>	1 1	RES/DSIR/EIB	1 1
	RES/DSR/PRAB	1 1	RGN5 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS,S	4 4	FORD BLDG HOY,A	1 1
	H ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC MAYS,G	1 1
	NSIC MURPHY,G.A	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 44 ENCL 43

R  
I  
D  
S  
/  
A  
D  
D  
S  
/  
A  
D  
D  
S  
/  
A  
D  
D  
S

1104  
ON



*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN  
STATION MANAGER

TELEPHONE  
(714) 368-6241

March 13, 1989

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket Nos. 50-361 and 50-362  
Follow-up Report, Inoperable Fire Doors - February 1989  
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, H. E. Morgan (SCE) to J. B. Martin (NRC),  
dated February 13, 1989

In accordance with our referenced letter, this submittal provides the follow-up report of Technical Specification fire-rated assemblies (specifically fire doors) found inoperable during routine surveillances in February 1989.

Fire doors found inoperable during the February routine surveillances are identified in the Attachment and include: 14 latching mechanism failures and 15 closure mechanism failures. No doors were found blocked open in February. As each of these deficiencies was identified, compensatory fire watches pursuant to Technical Specification 3.7.9, Action Statement "a", were established and will remain in effect until the door is restored to operable status.

31 139

8903300373 890313  
PDR ADOCK 05000361  
S PDC

IE22  
11  
000000


Mr. J. B. Martin

-2-

This monthly follow-up report and those sent previously provide updated information associated with an ongoing condition initially reported in 1983. The follow-up report covering inoperable fire doors identified in February will be submitted during April 1989.

If you require any additional information, please so advise.

Sincerely,

A handwritten signature in black ink, appearing to read "H. E. May", with a long horizontal stroke extending to the right.

Enclosure

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)  
U. S. Nuclear Regulatory Commission Document Control Desk  
Institute of Nuclear Power Operations (INPO)

ATTACHMENT  
SOUTHERN CALIFORNIA EDISON COMPANY  
INOPERABLE FIRE DOORS FOR THE MONTH OF FEBRUARY 1989  
SAN ONOFRE NUCLEAR GENERATING STATION  
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362

I. Latching Mechanism Failures:

Number of doors inoperable - 14, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
AC-118	01/21/89	02/17/89
S2-018	01/27/89	02/14/89
FH3-404	01/29/89	02/02/89
AC-223	02/05/89	02/13/89
AC-332	02/08/89	02/21/89
C3-406	02/11/89	02/21/89
AC-221	02/13/89	02/14/89
AC-242	02/14/89	02/15/89
AC-428	02/14/89	02/27/89
FH3-404	02/15/89	- - -
FH2-101	02/20/89	- - -
C3-406	02/25/89	- - -
FH3-101	02/25/89	- - -
DG3-104	02/26/89	- - -

II. Closure Mechanism Failures:

Number of doors inoperable - 15, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
AC-401	10/05/88	- - -
AC-423	10/06/88	- - -
FH2-404	01/16/89	02/02/89
AC-105	01/25/89	02/01/89
FH3-404	01/29/89	02/02/89
AC-259	01/31/89	- - -
FH2-207	02/04/89	02/06/89
AC-119	02/05/89	02/17/89
AC-223	02/05/89	02/13/89
AC-428	02/05/89	02/14/89
S2-018	02/05/89	02/14/89
AC-221	02/13/89	02/14/89
FH3-404	02/15/89	- - -
AC-221	02/20/89	02/21/89
FH2-101	02/20/89	- - -

III. Doors Blocked Open:

Number of doors blocked open - None

fdr'89/feb