

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8702040456 DDC DATE: 87/01/26 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern Californ 05000362
 AUTH. NAME AUTHOR AFFILIATION
 MEDFORD, M. O. Southern California Edison Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Responds to telcon request & forwards P&ID in order to
 facilitate review of utils response to IE Bulletin 85-003 re
 motor-operated valve common mode failure during plant
 transients due to improper switch settings.

DISTRIBUTION CODE: A055D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: OR/Licensing Submittal: Salem ATWS Events GL-83-28

NOTES: ELD Chandler icy. 05000361
 ELD Chandler icy. 05000362

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
PWR-B ADTS		1	1	PWR-B EB		1	1
PWR-B PEICSB		2	2	PWR-B FOB		1	1
PWR-B PD7 LA		1	0	PWR-B PD7 PD 01		3	3
ROOD, H		1	1	PWR-B PEICSB		1	1
PWR-B RSB		1	1				
INTERNAL: ACRS		6	6	ADM/LFMB		1	0
ELD/HDS2		1	0	IE/DI		1	1
IE/DQAVT		1	1	NRR LASHER, D		1	1
NRR PWR-A ADTS		1	1	NRR PWR-B ADTS		1	1
NRR TOALSTON, A		1	1	NRR/DSRO/RSIB		1	1
NRR/TAMB		1	1	REG FILE 04		1	1
EXTERNAL: LPDR	03	1	1	NRC PDR	02	1	1
NSIC	05	1	1				
NOTES:		1	1				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 33 ENCL 30



Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

January 26, 1987

M. O. MEDFORD
MANAGER OF NUCLEAR ENGINEERING
AND LICENSING

TELEPHONE
(818) 302-1749

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station
Units 2 and 3

Reference: IE Bulletin 85-03: Motor-Operated Valve Common Mode Failure
During Plant Transients Due to Improper Switch Settings

The above referenced IE Bulletin dated November 15, 1985 required all licensees to develop and implement a program to ensure that valve operator switches are selected, set and maintained properly. By letter dated May 19, 1986, SCE provided the NRC with the response to this Bulletin.

Subsequently, by telecon the week of December 1, 1986, the NRC (H. Rood) requested several (68) P&ID's to facilitate the review of SCE's response. The purpose of this letter is to provide the NRC with the requested P&ID's.

If you have any questions, please call me.

Very truly yours,

Enclosure: 1 (under separate cover to H. Rood)

2 (list of drawings with letter)

cc: H. Rood, NRC Senior Project Manager, San Onofre Units 2 and 3

F. R. Huey, NRC Senior Resident Inspector, San Onofre Units 1, 2 and 3

8702040456 870126
PDR ADCK 05000361
Q PDR

A055
1/1

ENCLOSURE

40111A REV.10
40111B REV.6
40111C REV.8
40111X REV.0
S03 40111A REV.6
S03 40111B REV.4
S03 40111C REV.5
S03 40111X REV.0
40112A REV.11
40112B REV.10
40112C REV.3
40112D REV.3
40112X REV.0
S03 40112A REV.8
S03 40112B REV.6
S03 40112C REV.2 3
S03 40112D REV.6
S03 40112X REV.0
40113A REV.4
40113B REV.5
40113X REV.0
S03 40113A REV.4
S03 40113B REV.5
S03 40113X REV.0
40122A REV.7
40122B REV.7
40122C REV.6
40122X REV.0
S03 40122A REV.3
S03 40122B REV.7
S03 40122C REV.3
S03 40122X REV.0
40141A REV.6
40141B REV.8
40141C REV.11
40141D REV.14
40141E REV.13
40141F REV.8
40141G REV.5
40141H REV.4
40141X REV.1
S03 40141A REV.4
S03 40141B REV.7
S03 40141C REV.9
S03 40141D REV.14
S03 40141E REV.13
S03 40141F REV.7
S03 40141G REV.2
S03 40141H REV.1
S03 40141X REV.1
40150A REV.3
40150B REV.5
40150C REV.7
40150D REV.11
40150X REV.1
S03 40150A REV.1
S03 40150B REV.5
S03 40150C REV.3
S03 40150D REV.5

S03 40150X REV.1
40160A REV.11
40160B REV.5
40160C REV.0
40160X REV.2
S03 40160A REV.5
S03 40160B REV.7
S03 40160C REV.0
S03 40160X REV.1