

RECEIVED
NRC

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

REGION V IAF

SCE

J. G. HAYNES
STATION MANAGER

March 21, 1985

TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Subject: Docket No. 50-361
Prompt Report and 14-Day Follow-up Report
License Condition 2.C.(14)a
San Onofre Nuclear Generating Station, Unit 2

Pursuant to License Condition 2.G to Facility Operating License NPF-10 for Unit 2, this submittal provides the written confirmation of our prompt notification and the 14-day Follow-up Report for an occurrence associated with USNRC Regulatory Guide 1.75.

License Condition 2.C.(14)a of Operating License NPF-10 requires that SCE maintain in effect and fully implement the Fire Protection Plan as delineated in the Fire Hazards Analysis (FHA). Section I.E.1 of the FHA, states that cable separation criteria shall be in accordance with USNRC Regulatory Guide 1.75, "Physical Independence of Electrical Systems."

On March 20, 1985, one Nonconformance Report (NCR) was identified which documents an incorrectly installed nonsafety-related cable which did not meet the applicable separation criteria of Regulatory Guide 1.75. This NCR was initially issued in September 1984, and scheduled for correction during the current outage, but was inadvertently omitted from the reportability review cycle.

The cause of the cable separation deficiency was apparently error in the initial installation of the nonsafety-related cable. The deficiency was corrected on February 11, 1985, by reworking the nonsafety-related cable to meet USNRC Regulatory Guide 1.75. No further action is planned.

To ensure no other NCRs were omitted from the reportability review cycle, an audit of all NCR's generated at SONGS during the last year was performed on March 20, 1985, which confirmed that all required reports have been made with this single exception. This audit encompassed over 3,500 NCR's for SONGS 1, 2 and 3.

8504080387 850321
PDR ADDCK 05000361
S PDR

10
IF-28

Mr. J. B. Martin

-2-

March 21, 1985

If you require additional information regarding the above, please so advise.

Sincerely,

JG Haggnes/wem

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

Institute of Nuclear Power Operations (INPO)