


Southern California Edison Company

P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

D. E. NUNN
MANAGER, QUALITY ASSURANCE

December 3, 1979

TELEPHONE
(213) 572-1695



Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94596

Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station, Units 2 and 3

In a letter to your office dated November 5, 1979 we identified a condition which we consider reportable in accordance with 10CFR50.55(e). This condition involves the lack of qualification testing documentation for electrical cable repaired by the manufacturer.

Due to the time required for investigation of the condition and for response to action requests we find it necessary to delay submittal of the final report until December 12, 1979.

If you have any questions regarding this matter, we would be pleased to discuss it with you at your convenience.

Very truly yours,

cc: R. J. Pate (NRC, San Onofre Units 2&3)

8001110186

79-156