

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR




Figure 2.5.2-227 Deaggregation of 10^{-5} Rock Hazard for 5 and 10 Hz