

# BED BATH & BEYOND<sup>®</sup>

**Harmon.**  
**STORES, INC.**  
A Bed Bath & Beyond Subsidiary



## Corporate Office

650 Liberty Avenue  
Union, NJ 07083  
908/688-0888

12-5-13

Director  
Office of Federal and State Materials and Environmental Management Programs  
ATTN: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

**Re: Transfer of Tritium Exit Signs  
Bed Bath & Beyond Store #1046, Allen Park, MI**

Dear Sir or Madam:

Pursuant to Michigan regulation, Bed Bath & Beyond Inc. ("BBB") provides this notice that on November 20, 2013, BBB transferred the self-luminous exit signs listed on the attached table from BBB Store #1046 located at Fairlane Green Shopping Center, 3180 Fairlane Drive, Allen Park, MI 48101 to Shield Source Inc., Attn: Taylor Perry, 925-211C Airport Road, Cavan Monaghan, ON K9J0E7 with license number CNSC # IL-A1-4790.0/2014. For each sign, the manufacturer name, model number, serial number, manufacture date, and original curie content are indicated on the attached tables.

Please contact me at 908-855-4294 if you have any questions regarding this letter or the attached report.

Sincerely,

Jim O'Connor

**Jim O'Connor**  
Bed Bath & Beyond Inc.  
Vice President - Loss Prevention and Safety

## Serial Number Spreadsheet (Box Contents)

Store #: 1046 Address: 3180 Fairlane Dr City, State: Allen Park, MI

- ☐ Fill out this form for each tritium exit sign going into a box
- ☐ Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- ☐ **FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store**
- ☐ **FAX to CB&I at 225-987-3228 BEFORE you leave the store**

RMA #: <u>9675 PA</u> Box <u>1</u> of <u>2</u> Weight of Box: <u>21.5 lbs</u> Total Curies in this box: <u>69</u>	<b>Do NOT exceed 99 curies per box</b>  8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.  Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
--	---

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	SLC	8/2005	SLX-60	335023	11.5
2	SLC	8/2005	SLX-60	335022	11.5
3	SLC	8/2005	SLX-60	335021	11.5
4	SLC	8/2005	SLX-60	335010	11.5
5	SLC	8/2005	SLX-60	335011	11.5
6	SLC	8/2005	SLX-60	335015	11.5
7					
8					
9					
10					

## Serial Number Spreadsheet (Box Contents)

Store #: 1046 Address: 3180 Fairlane Dr. City, State: Allen Park, MI

- ☐ Fill out this form for each tritium exit sign going into a box
- ☐ Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- ☐ FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- ☐ FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9675PA</u> Box <u>2</u> of <u>2</u> Weight of Box: <u>21.5</u> Total Curies in this box: <u>69</u>	<b>Do NOT exceed 99 curies per box</b>  8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.  Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
---	---

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	SLC	8/2005	SLX-60	335018	11.5
2	SLC	8/2005	SLX-60	335019	11.5
3	SLC	8/2005	SLX-60	335017	11.5
4	SLC	8/2005	SLX-60	335014	11.5
5	SLC	8/2005	SLX-60	335020	11.5
6	SLC	8/2005	SLX-60	335013	11.5
7					
8					
9					
10					