

WESCO Distribution
5 Germay Drive
Wilmington, DE. 19804

March 27th, 2014

Director of FSME
Attn: GLTS
USNRC
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on March 27th, 2014, we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2015. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Michael Joswick @ 302-655-9611

Sincerely,

Michael J. Joswick

WESCO Distribution
5 Germay Drive
Wilmington, DE. 19804

March 27th, 2014

Director of FSME
Attn: GLTS
USNRC
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on March 27th, 2014, we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2015. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Michael Joswick @ 302-655-9611.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael Joswick", written in a cursive style.

Michael Joswick



Serial Number Spreadsheet

Company Name	Wesco Distribution	Contact Name	Mike Joswick
Address 1	56 Germain Drive	Contact Phone	302-651-9722
Address 2		Contact Fax	302-655-9635
City/State	Wilmington, DE	Contact Email	M.Joswick@Wesco.com
Zip Code	19804	Today's Date	March 21st 2014

*Please completely fill out the above fields

Line	Manufacturer Name	Manufacturer Date	Model Number	Serial Number	Original Activity (CI or Tbg)
1	Evergl	Illegible	Illegible 710	29213	Illegible
2	Evergl	1-85	710	29215	25 carries
3	Illegible	Missing	Safety-10	ST-12576	21 carries
4	Missing	Missing	Safety-10	ST-12580	21 carries
5	Moduglo	6-86	700	9124	25 carries
6	Missing	Missing	Safety-10	ST-12578	21 carries
7	Missing	Missing	Safety-10	ST-12581	21 carries
8	SPL	6-87 Missing	710A Series	Missing	Missing
9	SPL	Missing	Missing	Missing	Missing
10	SPL	Missing	Missing	Missing	Missing
11	Evergl	5/95	710	5538	26 carries
12	SPL	Missing	Missing	Missing	Missing
13	SPR Evergl	12/94	710	5012	26 carries
14	Evergl	4/85	710	30246	25 carries
15	Evergl	9/84	710	27465	25 carries
16	SPL	Missing	Missing	Missing	Missing
17	SPL	Missing	Missing	Missing	Missing
18	Evergl	4-88	710	A-1041	25 carries
19	Evergl	9-84	710	27,460	25 carries
20	Evergl	9-84	710	27,459	25 carries
21	SPL	21-88 Missing	710A	5536	Missing
22	SPL	Missing	710A	5560	Missing
23	Evergl	Missing	15	5010	Missing
24	Evergl	Missing	10	5539	Missing
25					

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.