

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7910100223 DOC. DATE: 79/10/05 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261
 AUTH. NAME AUTHOR AFFILIATION
 BANKS, H. R. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director

SUBJECT: Forwards LERs 79-032/03L-0, 79-033/03L-0 & 79-034/03L-0.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Incident Reports

NOTES: -----

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	05 BC <u>ORB#1</u>	4 4			
INTERNAL:	01 <u>REG FILE</u>	1 1		02 NRC PDR	1 1
	09 I&E	2 2		11 MPA	3 3
	14 TA/EDO	1 1		15 NOVAK/KNIEL	1 1
	16 EEB	1 1		17 AD FOR ENGR	1 1
	18 PLANT SYS BR	1 1		19 I&C SYS BR	1 1
	20 AD PLANT SYS	1 1		22 REAC SAFT BR	1 1
	23 ENGR BR	1 1		24 KREGER	1 1
	25 PWR SYS BR	1 1		26 AD/SITE ANAL	1 1
	27 OPERA LIC BR	1 1		28 ACIDENT ANALYS	1 1
	29 AUX SYS BR	1 1		E JORDAN/IE	1 1
	HANAUER, S.	1 1		STS GROUP LEADR	1 1
	TMI-H STREET	1 1			
EXTERNAL:	03 LPDR	1 1		04 NSIC	1 1
	29 ACRS	16 16			

00112

ccf

TOTAL NUMBER OF COPIES REQUIRED: LTTR 48 ENCL 48

A04

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

223A

ACCESSION NBR: 7910100231 DOC. DATE: 79/10/05 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261
 AUTH. NAME AUTHOR AFFILIATION
 STARKEY, R. B. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Region 2, Atlanta, Office of the Director

SUBJECT: LER 79-032/03L-0: on 790905, motor operated isolation valve in
 AFW line to A S/G failed to open. Caused by operator power
 supply breaker trip. Breaker reset.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR -- ENCL -- SIZE: -----
 TITLE: Incident Reports

NOTES: -----

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR
	05 BC	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACIDENT ANALYS	1	1
	29 AUX SYS BR	1	1	E JORDAN/IE	1	1
	HANAUER, S.	1	1	STS GROUP LEADR	1	1
	TMI-H STREET	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

223B

ACCESSION NBR: 7910100238 DOC. DATE: 79/10/03 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261
 AUTH. NAME AUTHOR AFFILIATION
 STARKEY, R. B. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Region 2, Atlanta, Office of the Director

SUBJECT: LER 79-033/03L-0: on 790906, motor operated isolation valve in
 AFW line to A S/G failed to open. Caused by power supply
 breaker trip. Breaker reset.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR -- ENCL -- SIZE: -----
 TITLE: Incident Reports

NOTES: -----

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR
	05 BC	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACIDENT ANALYS	1	1
	29 AUX SYS BR	1	1	E JORDAN/IE	1	1
	HANAUER, S.	1	1	STS GROUP LEADR	1	1
	TMI-H STREET	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			



Carolina Power & Light Company

October 5, 1979

FILE: NG-3516 (R)

SERIAL: GD-79-2483

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORTS 79-32, 79-33, AND 79-34

Dear Mr. O'Reilly:

In accordance with Section 6.9.2.b.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Reports are submitted. These reports fulfill the requirement for a written report within thirty (30) days of a reportable occurrence and are in accordance with the format set forth in NUREG-0161, July, 1977.

Yours very truly,

H. R. Banks

Manager

Nuclear Generation

SBT:jnh*

Attachment

cc: Messrs. R. A. Hartfield
V. Stello

7910100 223

S

1002
5/11