

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S	C	H	B	R	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

REPORT SOURCE 60 L 61 0 62 5 63 0 64 0 65 0 66 2 67 6 68 1 69 7 70 0 71 9 72 0 73 5 74 7 75 9 76 8 77 1 78 0 79 0 80 5 81 7 82 9 83 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While using the AFW pumps to maintain S/G level, the motor operated isolation valve
0 3 | in the AFW line to "A" S/G (AFW-V2-16A) failed to open and was declared inoperable.
0 4 | This resulted in operation in a degraded mode permitted by T.S. 3.4.3 and constitutes
0 5 | a reportable occurrence per T.S. 6.9.2.b.2. Throughout the event both main feedpumps
0 6 | and both motor driven AFW pumps were available. Also, V2-16A was manually operable if
0 7 | required. Therefore, there was not threat to either plant or public safety.
0 8 |

SYSTEM CODE H H 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE V A L V O P 14				COMP. SUBCODE A 15		VALVE SUBCODE Z 16					
LER/RO REPORT NUMBER 7 8		EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 3 2 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32							
ACTION TAKEN E 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED Y 23 41		NPRD-4 FORM SUB. Y 24 42		PRIME COMP. SUPPLIER A 25 43		COMPONENT MANUFACTURER L 2 0 0 0 26 44 47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The Limitorque SMB-00 operator mounted on V2-16A failed to operate on an open signal

1 1 due to the operator power supply breaker having tripped. The root cause of the failure

1 2 is still under investigation. The breaker was reset and the valve was declared oper-

1 3 able after having been stroked several times with no problems. The valve was inoper-

1 4 able for less than one hour.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 G 0 0 0 NA A Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) NA

7 8 9 10 11 44

NA LOCATION OF RELEASE (36)

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) NA	(39)		

		PERSONNEL INJURIES				
		NUMBER	DESCRIPTION (41)			
1	8	0	0	0	(40)	NA

7		8	9	11	12	80
		LOSS OF OR DAMAGE TO FACILITY (43)				
		TYPE		DESCRIPTION		
1	9	Z	(42)	NA		

7	8	9	10											80		
PUBLICITY																
ISSUED		DESCRIPTION		7910100 231											NRC USE ONLY	
2	0	N	NA	S												
7	8	9	10											68	69	80

NAME OF PREPARER R. B. Starkey, Jr.

PHONE: 803-383-4524