



Carolina Power & Light Company

Central File
50-261

July 31, 1978

File: NG-3513 (R)

Serial: GD-78-1978

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. ~~DPR-23~~
RESPONSE TO IE BULLETIN 78-10

Dear Mr. O'Reilly:

No Bergen-Paterson Hydraulic Shock Suppressors are in use on safety-related systems at Robinson Unit No. 2. Also the three Bergin-Paterson Suppressors installed on the secondary steam dump system do not have serial numbers corresponding to those listed in the IE Bulletin.

Yours very truly,

H. R. Banks
Manager
Nuclear Generation

HSZ:DCS:mvp*

cc: Mr. E. Volgenau

A102

ccp