

Carolina Power & Light Company

April 18, 1974

67-261  
File: NG-3513

Serial: NG-74-469


Mr. Norman C. Moseley, Director  
Directorate of Regulatory Operations  
U. S. Atomic Energy Commission  
Region II, Suite 818  
230 Peachtree Street, N.W.  
Atlanta, Georgia 30303

Dear Mr. Moseley:

H. B. ROBINSON UNIT NO. 2  
LICENSE NO. DPR-23  
DRO BULLETIN NO. 74-3

In response to DRO Bulletin 74-3 of March 22, 1974, concerning Failure of Structural or Seismic Support Bolts on Class I Components, the requested inspections will be performed during the refueling outage beginning May 4, 1974. The written program and procedures will be available for RO Inspection by May 15, 1974.

Yours very truly,

  
E. E. Utley  
Vice-President  
Bulk Power Supply

ACT:DBW:mvp

cc: Messrs. N. B. Bessac  
B. J. Furr  
W. B. Howell  
D. V. Menscer  
D. B. Waters

Letter from Carolina Power and Light Company, E. E. Utley,  
dated April 18, 1974 - ROB 74-3 - 50-261

APR 23 1974

DISTRIBUTION:

H. D. Thornburg

RO:HQ (4)

Directorate of Licensing (4)

DR Central Files

PDR

Local PDR

NSIC

OIS, OR