



Carolina Power & Light Company

May 7, 1973

Mr. Norman C. Moseley
Directorate of Regulatory Operations
U. S. Atomic Energy Commission
Region II - Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

Dear Mr. Moseley:

H. B. ROBINSON UNIT NO. 2
LICENSE DPR-23
RO:II:WWP
RO INQUIRY REPORT NO. 50-261/73-2Q

In your letter dated April 25, 1973, you requested that we inform you in writing as to the proprietary or non-proprietary nature of the information contained in your attached RO Inquiry Report No. 50-261/73-2Q. We have reviewed the report and state that there is no information of a proprietary nature contained therein.

Very truly yours,

E. E. Utley
Vice-President
Bulk Power Supply

DBW/mp

cc: Mr. C. D. Barham
Mr. N. B. Bessac
Mr. B. J. Furr
Mr. D. V. Menscer

MAY 15 1973

Letter from Carolina Power and Light Company, E. E. Utley
dated May 7, 1973 - 50-261/73-2Q

DISTRIBUTION:

H. D. Thornburg, RO (2)

RO:HQ (5)

DR Central Files

Regulatory Standards (3)

Directorate of Licensing (13)

PDR

Local PDR

NSIC

OIS, OR

State



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE: (404) 826-4503

APR 30 1973

J. G. Keppler, Chief, Operations Branch (2)
Directorate of Regulatory Operations, Headquarters

RO INQUIRY REPORT NO. 50-261/73-3Q
CAROLINA POWER AND LIGHT COMPANY (H. B. ROBINSON NO. 2), LICENSE
NO. DPR-23, DOCKET NO. 50-261, UNCONTROLLED LOSS OF CONTAMINATED
REFUELING WATER TO OFFSITE DRAINAGE

The attached Inquiry Report is forwarded for information.

This is the second uncontrolled offsite release within two weeks
and resulted from operator error and lack of high level alarm pro-
tection on the refueling water storage tank. Our concern regarding
the lack of high level alarm was forwarded to D. F. Knuth, Deputy
Director for Field Operations, Directorate of Regulatory Operations,
Headquarters, in a memorandum dated April 25, 1973. The licensee's
corrective actions will be reviewed during the next scheduled
inspection.

A copy of the licensee's telegram informing Region II of the release
is attached to the Inquiry Report.

e. m. Upright for
W. C. Seidle, Chief
Facilities Operations Branch

RO:II:CMU

Enclosure:
RO Inquiry Rpt. No.
50-261/73-3Q

cc w/encl:
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Directorate of Licensing (13)
J. P. O'Reilly, RO:I

cc encl. only:
*PDR
*Local PDR
*NSIC
*DTIE, OR
*State

*To be dispatched at a later date.

21