



50-261  
Telegram

OEERP EDT JUN 21 73 AA142 AAD195(1429)(2-234333E172)PD

06/21/73 1429

ICS IPMMTZZ CSP

8033321351 TDMT HARTSVILLE SC 118 06-21 0229P EST

PMS NORMAN C MOSELY DIRECTOR *J. J. Rm 818*

REGION 2 AEC DIRECTORAGE REGULATORY OPERATIONS DRL 230 PEACHTREE  
ST

ATLANTA GA 30303

IN ACCORDANCE WITH 6.6.2 OF THE TECHNICAL SPECIFICATION, THE  
FOLLOWING ABNORMAL OCCURENCE IS REPORTED: ON JUNE 20, 1973,  
AT 1454 HOURS WHILE PERFORMING A TEST OF THE TURBINE REDUNDANT  
OVERSPEED TRIP SYSTEM (TROTS) A TURBINE TRIP OCCURRED. AN IMMEDIATE  
REACTOR TRIP DID NOT OCCUR DUE TO A TURBINE STOP VALVE LIMIT  
SWITCH MALFUNCTION. A REACTOR TRIP DID OCCUR DUE TO HIGH PRESSURIZER  
PRESSURE.

THE TURBINE STOP VALVE LIMIT SWITCH WAS ADJUSTED AND SATISFACTORILY  
OPERATED PRIOR TO INITATING POWER OPERATION.

THE INCIDENT HAS BEEN REVIEWED BY THE PLANT NUCLEAR SAFETY COMMITTEE  
AND SAFE REACTOR OPERATION IS ASSURED.

THIS WAS REPORTED TO MR SIEDLE OF DRO BY TELEPHONE ON JUNE 21  
1973

B J FURR PLANT MGR CAROLINA POWER AND LIGHT CO H B ROBINSON  
SEG PLANT HARTSVILLE SC PO BOX 790 29550

JUN 22 1973

Telegram from Carolina Power and Light Company,  
B. J. Furr, dated June 21, 1973 - 50-261

cc w/encl:

H. D. Thornburg (2), RO

RO:HQ (5)

→ DR Central Files

Regulatory Standards (3)

Directorate of Licensing (13)

cc encl. only:

PDR

Local PDR

NSIC

DTIE, OR

State