

214P EDT JUN 6 73 AB154 AAD175(1249)(2-102498E157)PD

06/06/73 1249

ICS IPMMTZZ CSP

8033321351 TDMT HARTSVILLE SC 143 06-06 1249P EST
PMS MR NORMAN C MOSELY DIRECTOR REGION 2 AEC DIRECTORATE OF
REGULATORY OPERATION, DLR
230 PEACHTREE ST
ATLANTA GA 30303

IN ACCORDANCE WITH SECTION 6.6.2 OF THE TECHNICAL SPECIFICATION,
THE FOLLOWING ABNORMAL OCCURANCE IS REPORTED:

AT 1430 HOURS ON 6-5-73, WHILE INVESTIGATING AND ABNORMAL INDICATION
ON THE NARROW RANGE CONTAINMENT PRESSURE INDICATUR, IT WAS
FOUND THAT 3 3/8 INCH VENT VALVES ON THE PRESSURE SENSING LINE
TO ALL CONTAINMENT PRESSURE TRANSMITTERS WERE OPEN. THIS RESULTED
IN ERRONEOUS SIGNALS TO PT'S 950, 951, 952, 953, 954, AND 955,
WHICH SUPPLY INPUTS TO RTGB INDICATORS AND SAFEGUARD RACKS.

SF-1201 (R5-69)

THE VENT VALVES WERE CLOSED AND PLUGS INSTALLED TO PREVENT RECURRENCE
OF THIS INCIDENT. AS A FURTHER PRECAUTION, THESE VALVES HAVE
BEEN ADDED TO THE CHECK OFF SHEET WHICH ESTABLISHES CONTAINMENT
INTEGRITY.

THIS INCIDENT HAS BEEN REVIEWED BY THE PLANT NUCLEAR SAFETY
COMMITTEE AND SAFE REACTOR OPERATION IS ASSURED.

SF-1201 (R5-69)

THIS WAS REPORTED TO MR BILL SIEDLE OF DRO BY TELEPHONE ON 6-6-73.

MR BENNY J FURR, MANAGER /H B ROBINSON SEG PLANT


JUN 7 1973

Telegram from Carolina Power and Light Company,
Benny J. Furr, dated 6/6/73 - 50-261

cc w/encl:

H. D. Thornburg(2), RO

RO:HQ (5)

 DR Central Files

Regulatory Standards (3)

Directorate of Licensing (13)

PDR

Local PDR

NSIC

OIS, OR

State