

November 24, 1976

File: NG-3513 (R)

Serial: NG-76-1504


Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 818
230 Peachtree Street, N. W.
Atlanta, Georgia 30303

H. B. ROBINSON UNIT NO. 2
LICENSE NO. DPR-23
DOCKET NO. 50-261
RESPONSE TO IE CIRCULAR 76-05

Dear Mr. Moseley:

IE Circular 76-05 identified possible improper lock-up and bleed rates on certain ITT Grinnell shock and sway suppressors (snubbers). We have reviewed the information regarding the identified snubbers and have found that none of these specific snubbers are in use at the H. B. Robinson Plant. Consequently, no further action is planned regarding Circular 76-05.

Very truly yours,



H. R. Banks
Manager
Nuclear Generation

KEB/CSB/bb

cc: Mr. W. G. McDonald
Mr. E. Volgenau

AC2

T