

*Kratty Facilitates
Per.*

April 16, 1976

File: NG-3513 (R)

Serial: NG-76-530


Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

Dear Mr. Moseley:

H. B. ROBINSON UNIT NO. 2 50-261
LICENSE NO. DPR-23
RESPONSE TO IE BULLETINS 76-02 AND 76-03

Your letter of March 16, 1976, transmitted IE Bulletins 76-02 and 76-03 relating to possible generic problems associated with specified types of GE relays. An investigation of the Robinson QA files and a walk-through of safety related systems has confirmed that no relays of the specified types are installed at H. B. Robinson Unit 2. No further action is planned with regard to IE Bulletins 76-02 and 76-03.

Yours very truly,


E. E. Utley
Vice President
Bulk Power Supply

CSB:jwk

cc: Messrs. W. G. McDonald
E. Volgenan

9