

Acc 2

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-261 H B ROBINSON 2
RECIPIENT: O'REILLY, J.P.
ORIGINATOR: BANKS, H.R.
COMPANY NAME: CAROLINA PWR & LIGHT
SUBJECT:

DOC DATE: 781016
ACCESSION NBR: 7810270215
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+1

LER#78-026/01T-0 on 781003: During normal oper "A" & "B" Containment
Spray Pumps failed to meet P req due to air binding. Pumps vented at
2150 making them oper.

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
K SEYFRIT/IE	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

TOTAL NUMBER OF COPIES REQUIRED:
LTR
ENCL

42
42

NOV 1 1978

NOTES:



Carolina Power & Light Company

October 16, 1978

FILE: NG-3516 (R)

SERIAL: GD-78-2797

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 1217
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

REGULATORY DOCKET FILE COPY

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORT 78-026

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Report is submitted. This report fulfills the requirement for a written report within fourteen (14) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July, 1977.

Yours very truly,

H. R. Banks
Manager
Nuclear Generation

DCS:cp*

Attachment

cc: Messrs. R. A. Hartfield
John G. Davis