

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9101290098 DOC. DATE: 91/01/24 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261

AUTH. NAME AUTHOR AFFILIATION
 SHEPPARD, J.J. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 901229, Fire Door 32 exceeded seven day
 inoperable limit allowed by Tech Spec 3.14.7.2.c. Door made
 inoperable on 901222 for ongoing mods in pipe alley. Door
 will be made operable on or before 910215.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES		
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL	
	PD2-1 LA		1	1		PD2-1 PD		1	1	
	LO, R		1	1						
INTERNAL:	ACNW		2	2		AEOD/DOA		1	1	
	AEOD/DSP/TPAB		1	1		AEOD/ROAB/DSP		2	2	
	NRR/DET/ECMB 9H		1	1		NRR/DET/EMEB 7E		1	1	
	NRR/DLPQ/LHFB11		1	1		NRR/DLPQ/LPEB10		1	1	
	NRR/DOEA/OEAB		1	1		NRR/DREP/PRPB11		2	2	
	NRR/DST/SELB 8D		1	1		NRR/DST/SICB 7E		1	1	
	NRR/DST/SPLB8D1		1	1		NRR/DST/SRXB 8E		1	1	
	REG FILE 02		1	1		RES/DSIR/EIB		1	1	
	RGN2 FILE 01		1	1						
EXTERNAL:	EG&G BRYCE, J.H		3	3		L ST LOBBY WARD		1	1	
	NRC PDR		1	1		NSIC MAYS, G		1	1	
	NSIC MURPHY, G.A		1	1		NUDOCS FULL TXT		1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 0

IA 2
 wlt



Carolina Power & Light Company

ROBINSON NUCLEAR PROJECT DEPARTMENT
POST OFFICE BOX 790
HARTSVILLE, SOUTH CAROLINA 29550

JAN 24 1991

Robinson File No: 13510H

Serial: RNP/91-0182

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
SPECIAL REPORT ON FIRE DOOR

Gentlemen:

Carolina Power and Light Company submits this Special Report in accordance with H. B. Robinson Unit No. 2 Plant Technical Specifications 3.14.7.2.c and 6.9.3.1.d.

Specifically Fire Door 32 located between the Pipe Alley and the Auxiliary Building Hallway has been inoperable for a period of time exceeding seven days. The door was made inoperable at 0420 on December 22, 1990, and exceeded the seven day limit allowed by Technical Specification 3.14.7.2.c at 0420 on December 29, 1990; this requires a thirty day Special Report pursuant to this Specification and Technical Specification 6.9.3.1.d. While the fire door was inoperable, compensatory action per Technical Specification 3.14.7.2 was maintained.

Fire Door 32 is blocked open by temporary cables, air hoses, and ventilation duct needed for modifications ongoing in the Pipe Alley. The door was declared inoperable at a time when equipment located in the Pipe Alley was required to be operable to support fuel reload. The modification work in the Pipe Alley is near completion and Fire Door 32 will be made operable on or before February 15, 1991.


9101290098 910124
PDR ADOCK 05000261
S PDR

IE22
1/0

U. S. Nuclear Regulatory Commission
Serial: RNP/91-0182
Page 2

Should you have any questions regarding this report, please contact
Mr. J. D. Kloosterman at (803) 383-1491.

Very truly yours,



J. J. Sheppard
General Manager

H. B. Robinson S. E. Plant

DAB:td

cc: Mr. M. L. Ernst
Mr. L. W. Garner
INPO