

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9211040153 DOC. DATE: 92/10/30 NOTARIZED: NO DOCKET #
 FACID: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
 AUTH. NAME AUTHOR AFFILIATION
 CHAMBERS, R.H. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 920528, Laundry & Hot Shower Room taken out of svc because it would not close properly & 7 day LCO entered. Caused by broken door knob. Fire Door restored to operable status on 920615.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-1 LA		1	1		PD2-1 PD		1	1
	MOZAFARI, B		1	1					
INTERNAL:	ACNW		2	2		AEOD/DOA		1	1
	AEOD/DSP/TPAB		1	1		AEOD/ROAB/DSP		2	2
	NRR/DET/EMEB 7E		1	1		NRR/DLPQ/LHFB10		1	1
	NRR/DLPQ/LPEB10		1	1		NRR/DOEA/OEAB		1	1
	NRR/DREP/PRPB11		2	2		NRR/DST/SELB 8D		1	1
	NRR/DST/SICB8H3		1	1		NRR/DST/SPLB8D1		1	1
	NRR/DST/SRXB 8E		1	1		REG FILE 02		1	1
	RES/DSIR/EIB		1	1		RGN2 FILE 01		1	1
EXTERNAL:	EG&G BRYCE, J.H		2	2		L ST LOBBY WARD		1	1
	NRC PDR		1	1		NSIC MURPHY, G.A		1	1
	NSIC POORE, W.		1	1		NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 29 ENCL 29

IA



Carolina Power & Light Company

ROBINSON NUCLEAR PROJECT DEPARTMENT
POST OFFICE BOX 790
HARTSVILLE, SOUTH CAROLINA 29550

OCT 30 1992

Robinson File No.: 13510H

Serial: RNP/92-2889

United States Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23

SPECIAL REPORT REGARDING INOPERABLE FIRE PROTECTION EQUIPMENT

Gentlemen:

Carolina Power and Light Company hereby provides this Special Report in accordance with H. B. Robinson Unit 2 Plant Technical Specifications. Specifically, Fire Protection equipment required by Technical Specifications 3.14.7.2 exceeded its respective LCO due to an equipment malfunction.

On May 28, 1992, Fire Door No. 18, entrance to the Laundry and Hot Shower Room, was taken out of service because it would not close properly, and a 7 day LCO was entered. In accordance with Technical Specification 3.14.7.2.a, the Fire Detection System providing coverage for the associated fire area was verified to be operable within one hour. A Work Request was written to repair the door. The LCO was exceeded on June 4, 1992, at 1642 hours, and the action statement of Technical Specification 3.14.7.2.c was entered. This action requires that a Special Report be prepared and submitted outlining the action taken, the cause of the inoperability, and the plans and schedule for restoring the fire barrier to service.

An Adverse Condition Report was initiated in accordance with the Corrective Action Program on October 1, 1992, that identified this condition and initiated a root cause investigation. The cause of the failure of Fire Door No. 18 to close is at this time attributed to a combination of a broken door knob and a change in ventilation system air flow in the room, which applied excessive pressure against the door such that the door could not completely close and latch on its own power.

9211040153 921030
PDR ADOCK 05000261
S PDR


IE 27, 1

Letter to U. S. Nuclear Regulatory Commission
Serial: RNP/92-2889
Page 2

A new door knob was installed on May 29, 1992. The Fire Door was restored to operable status on June 15, 1992, at 0930 hours when the ventilation system was adjusted to relieve air flow pressure against the door. This report is submitted pursuant to Technical Specification 3.14.7.2.c.

Should you have any questions regarding this matter, please contact Mr. J. L. Harrison at (803) 383-1433.

Very truly yours,

A handwritten signature in cursive script, appearing to read "R. H. Chambers for".

R. H. Chambers
General Manager
Robinson Nuclear Project Department

RDC:sgk

cc: Mr. S. D. Ebnetter
Mr. L. W. Garner
INPO