

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9312080195 DOC. DATE: 93/12/03 NOTARIZED: YES DOCKET #  
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261

AUTH. NAME AUTHOR AFFILIATION  
 DIETZ, C.R. Carolina Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Provides follow-up rept re completion of requested actions  
 of NRC Bulletin 93-002, "Debris Plugging of Emergency Core  
 Cooling Suction Strainers."

DISTRIBUTION CODE: IE11D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2  
 TITLE: Bulletin Response (50 DKT)

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 PD	1	MOZAFARI, B	1
INTERNAL:	AEOD/DOA	1	NRR/DE/EMEB	1
	NRR/DORS/OGCB	1	NRR/DRPW	1
	NRR/DRSS/PEPB	1	NRR/DSSA	1
	NRR/DSSA/SRXB	1	NRR/PDLII-2	1
	NRR/SCSB	1	<u>REG FILE</u> 02	1
	RES/DSIR/EIB	1	RGN2 FILE 01	1
EXTERNAL:	NRC PDR	1	NSIC	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL ~~16~~ 0



Carolina Power & Light Company  
Robinson Nuclear Plant  
PO Box 790  
Hartsville SC 29550

Robinson File No: 13510A  
Serial: RNP/93-2904

**DEC 03 1993**

United States Nuclear Regulatory Commission  
ATTENTION: Document Control Desk  
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261/LICENSE NO. DPR-23  
FOLLOWUP REPORT TO NRC BULLETIN NO. 93-02, "DEBRIS  
PLUGGING OF EMERGENCY CORE COOLING SUCTION STRAINERS"

Gentlemen:

The purpose of this letter is to provide a follow-up report regarding completion of the requested actions of NRC Bulletin No. 93-02 for the H. B. Robinson Steam Electric Plant, Unit No. 2 (HBR2).

On June 10, 1993, CP&L's letter in response to NRC Bulletin No. 93-02 stated that HBR2 had a possible source of loose fibrous filters in the containment vessel air handling units. HBR2 proposed to verify the adequacy of the existing design under the postulated conditions and secure these filters if necessary. This was completed as scheduled prior to the startup from Refueling Outage 15.

HBR2 will operate without these roughing filters in HVH-1 through HVH-4. During the current forced outage and during refueling outages in the future when the Reactor Coolant System (RCS) is below 200 degrees, the fibrous material filters will be reinstalled to provide filtered air through the coils. These filters will again be removed prior to the unit going above 200 degrees.

060028

9312080195 931203  
PDR ADOCK 05000261  
Q PDR



Highway 151 and SC 23 Hartsville SC

JEH  
1/0

A special procedure is being developed to perform a monthly inspection for evaluation of the HVH units. This inspection will include a visual inspection of the coils to determine the effects of operating without the filters. A differential pressure measurement across the coil in the primary unit will be taken on a monthly basis to assure adequate air flow is maintained. Also, the differential pressure across each HVH unit fan will be taken for trending purposes. Base line data is being taken as a reference in which to trend the monthly performance data. There may be a replacement of the filters, if necessary, using other than fibrous filter material, if a need for replacement is identified. A stainless steel filter is presently being evaluated to determine if it will be adequate as a replacement filter.


Questions regarding this matter may be referred to Mr. Jan S. Kozyra at (803) 383-1872.

Very truly yours,



Charles R. Dietz  
Vice President

I, C. R. Dietz, having been first duly sworn, did depose and say that the information contained herein is true and correct to the best of my information, knowledge and belief; and the sources of my information are officers, employees, contractors, and agents of Carolina Power & Light Company.

  
Notary (Seal)

My commission expires: JUNE 11, 1994

DTG:lst

c: Mr. S. D. Ebnetter  
Ms. B. L. Mozafari  
Mr. W. T. Orders