

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9510170284 DOC. DATE: 95/10/08 NOTARIZED: NO DOCKET #
FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
AUTH. NAME AUTHOR AFFILIATION
KRICH, R.M. Carolina Power & Light Co.
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Submits revised corrective action date contained in response
to violations noted in Insp Rept 50-262/95-13, per GL 88-05.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 PD	1 1	MOZAFARI, B	1 1
INTERNAL:	AEOD/DEIB	1 1	AEOD/SPD/RAB	1 1
	AEOD/TTC	1 1	DEDRO	1 1
	FILE CENTER	1 1	NRR/DISP/PIPB	1 1
	NRR/DORS/OEAB	1 1	NRR/DRCH/HHFB	1 1
	NUDOCS-ABSTRACT	1 1	OE DIR	1 1
	OGC/HDS3	1 1	RGN2 FILE 01	1 1
INTERNAL:	LITCO BRYCE, J H	1 1	NOAC	1 1
	NRC PDR	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 17 ENCL 17

**Carolina Power & Light Company**

Robinson Nuclear Plant
3581 West Entrance Road
Hartsville SC 29550

RNP File No: 13510E
Serial: RNP-RA/95-0179
OCT 08 1995

United States Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
NRC INSPECTION REPORT NO. 50-261/95-13
REVISION TO CORRECTIVE ACTION COMPLETION DATE

Gentlemen:

The purpose of this letter is to revise a corrective action completion date contained in our reply to the Notice of Violation in NRC Inspection Report No. 50-261/95-13, provided by letter dated July 17, 1995. The identified corrective actions to the violation in our reply stated that Procedure Plant Program (PLP)-040, "Program for Prevention of Boric Acid Corrosion of RCS Carbon Steel Bolting (GENERIC LETTER 88-05)," would be revised to consolidate American Society of Mechanical Engineers Boiler and Pressure Vessel Code, Section XI requirements relevant to the conduct of boric acid corrosion evaluations within the appropriate procedure section, and to clarify expectations regarding acceptable visual examination methods. We committed to full compliance by September 9, 1995. Due to an administrative oversight, this commitment was not satisfied until September 29, 1995, when the revised procedure PLP-040 was made effective. A review was conducted of commitments contained in 1995 violation responses, and no other similar administrative errors were found.

Questions regarding this matter may be referred to Mr. A. L. Garrou at (803) 857-1544.

Very truly yours, -

R. M. Krich
Manager - Regulatory Affairs

170081

DTG/klb

9510170284 951008
PDR ADDCK 05000261
Q PDR

c: Mr. S. D. Ebnetter, Regional Administrator, USNRC, Region II
Ms. B. L. Mozafari, USNRC Project Manager, HBRSEP
Mr. W. T. Orders, USNRC Senior Resident Inspector, HBRSEP

JE01 1/0