



Carolina Power & Light Company

June 15, 1977

Central File
50-261

File: NG-3513 (R)

Serial: NG-77-685

Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
RHR SYSTEM PIPE RESTRAINTS

Dear Mr. Moseley:

In January 1976 the Nuclear Regulatory Commission was notified by phone about certain Residual Heat Removal System pipe restraints at the H. B. Robinson Plant that were in need of repair. These restraints are located on the pipes between each RHR pump and its respective heat exchanger.

Following the notification, plant maintenance and engineering personnel examined and temporarily repaired each of the restraints. Ebasco Services then provided assistance in designing permanent repairs on the affected supports. These permanent corrections have now been completed and the supports are functioning satisfactorily.

Yours very truly,

H. R. Banks
Manager
Nuclear Generation

HSZ/CSB/pap

Misc
4
[Signature]