

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912270383 DOC. DATE: 79/12/19 NOTARIZED: YES DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261
 AUTH. NAME: UTLEY, E.E. AUTHOR AFFILIATION: Carolina Power & Light Co.
 RECIPIENT NAME: EISENHUT, D.G. RECIPIENT AFFILIATION: Division of Operating Reactors

SUBJECT: Confirms that mod to shed automatically pressurizer heaters from emergency power sources upon safety injection initiation will be installed by 800101.

DISTRIBUTION CODE: A039S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Resp to Lesson Learn Task Force - Westinghouse

NOTES: _____

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
INTERNAL:	10 BC <u>ORB #1</u>	1	1	17 I & E	2	2
	19 TA/EDU	1	1	2 NRC PDR	1	1
	20 CORE PERF BR	1	1	21 ENG BR	1	1
	22 REAC SFTY BR	1	1	23 PLANT SYS BR	1	1
	24 EEB	1	1	25 EFLT TRT SYS	1	1
	3 LPDR	1	1	4 NSIC	1	1
	5 J OLSHINSKI	1	1	6 J KERRIGAN	1	1
	7 J BURDION	1	1	8 C WILLIS	1	1
	9 G IMBRO	1	1	M FIELDS	1	1
	N ANDERSON	1	1	OELD	1	0
	P O'REILLY	1	1			
EXTERNAL:	26 ACRS	16	16			

JAN 2 1980

MA

TOTAL NUMBER OF COPIES REQUIRED: LTR 45 ENCL 0

12B



Carolina Power & Light Company

December 19, 1979

FILE: NG-3514(R)

SERIAL NO.: GD-79-3247

Mr. Darrell G. Eisenhut, Acting Director
Division of Operating Reactors
United States Nuclear Regulatory Commission
Washington, D.C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2

DOCKET NO. 50-261

LICENSE NO. DPR-23

STATUS OF SHORT TERM LESSONS LEARNED REQUIREMENTS

Dear Mr. Eisenhut:

Our letter of December 17, 1979 detailed the status of Short Term Lessons Learned requirements at the H. B. Robinson plant. In that letter we indicated that the modification to automatically shed the pressurizer heaters from the emergency power sources upon safety injection initiation might not be completed by January 1, 1980. This letter is to confirm that a modification will be installed by January 1, 1980, which will automatically trip the pressurizer heaters if they are being powered from emergency power and a safety injection actuation signal is activated.

As discussed with members of your staff (J. D. Neighbors and J. Olsinski), the modification that will be in place on January 1, 1980, is not the same modification package that was referred to in our December 17, 1979, letter. It will, however, meet the requirements of Item 2.1.1. We will provide details of this modification by December 31, 1979 in a package that details our compliance with all Short Term Lessons Learned requirements. As requested by your staff, we will continue to evaluate both Pressurizer Heater Modifications and will inform you of our decision concerning which modification we intend to have installed permanently.

A039
S
1/0

7912270

411 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602


7912270 383

Mr. Darrell G. Eisenhut

-2-

If you have any questions concerning this subject, please contact our staff.

Yours very truly,



E. E. Utley
Executive Vice President
Power Supply & Customer Services

JJS/jcb

Sworn to and subscribed to before me this 19th day of December, 1979.


Notary Public

My Commission expires October 4, 1981.

cc: Mr. J. D. Neighbors (NRC)
Mr. J. Olsinski (NRC)

