

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8405110086 DOC. DATE: 84/05/07 NOTARIZED: NO DOCKET #  
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261  
 AUTH. NAME AUTHOR AFFILIATION  
 MORGAN, R.E. Carolina Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 VARGA, S.A. Operating Reactors Branch 1

SUBJECT: Forwards "CP&L HB Robinson Unit 2 Nov 1983 Steam Generator  
 Outage Steam Generator Insp & Repair Rept."

DISTRIBUTION CODE: A001S *"see rept"* COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 11500  
 TITLE: OR Submittal: General Distribution

## NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
NRR ORB1 BC 01	7 1		
INTERNAL: ELD/HDS1	1 0	NRR/DE/MTEB	1 0
NRR/DL DIR	1 0	NRR/DL/ORAB	1 0
NRR/DSI/METB	1 0	NRR/DSI/RAB	1 0
<u>REG FILE</u> 04	1 1	RGN2	1 0
EXTERNAL: ACRS 09	6 0	LPDR 03	1 1
NRC PDR 02	1 1	NSIC 05	1 1
NTIS	1 1		

*Limited Distribution*



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT  
Post Office Box 790  
Hartsville, South Carolina 29550

MAY - 7 1984

Robinson File No: 13510

Serial: RSEP/84-67

Mr. Steven A. Varga, Chief  
Operating Reactors Branch No. 1  
Office of Nuclear Reactor Regulation  
United States Nuclear Regulatory Commission  
Washington, D. C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23

NOVEMBER 1983 STEAM GENERATOR EDDY CURRENT INSPECTION AND REPAIR REPORT

Dear Mr. Varga:

This letter transmits Carolina Power & Light Company's (CP&L) H. B. Robinson Unit No. 2, November 1983 Steam Generator Eddy Current Inspection Report. The report covers both inspection results and the repairs which were made as a result of the Eddy Current Inspection.

In January 1984, CP&L began a Steam Generator Repair Outage which will result in the replacement of the existing steam generator tube bundles. Since the old tube bundles will no longer be in service, this report is provided for historical reasons and does not contain a justification for continued operation.

Should you have any questions prior to these discussions, please contact my staff.

Very truly yours,

R. E. Morgan  
General Manager  
H. B. Robinson S. E. Plant

8405110086 840507  
PDR ADOCK 05000261  
G PDR

GH/pam

Enclosure

cc: J. P. O'Reilly, w/o Attachment to Appendix  
G. Requa, w/o Attachment to Appendix  
S. P. Weise, w/o Attachment to Appendix

Acc'd  
1/1  
Limited Dist: