



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina 29550

JUN 18 1980

Robinson File No. 2-0-4-a-3

Serial: RSEP/80-906

Mr. James P. O'Reilly, Director
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
REVISION TO LICENSEE EVENT REPORT 80-013

Dear Mr. O'Reilly:

Enclosed is Revision 1 to LER 80-013. It is being submitted to correct an error in the report type and occurrence code under Item 17 of the LER form.

In Revision 0, the occurrence code and report type incorrectly identified the event as a reportable occurrence requiring a 30-day written report. This revision corrects this error and correctly identifies the event as reportable requiring immediate notification and a follow-up report within fourteen (14) days. This Licensee Event Report (80-013) was reported to the Region II staff on May 18, 1980 and the written report was submitted on May 30, 1980 meeting all reporting requirements.

If you have questions concerning this report, please contact me.

Very truly yours,

R. B. Starkey, Jr.
General Manager

H. B. Robinson S.E. Plant

SWF/tg

Enclosure

cc: R. A. Hartfield (3) w/enclosure
V. Stello (40) w/enclosure

A002
3
1/1

8006230 572