

August 6, 1980

50 AUG 11 9:49

FILE: NG-3513 (R)

SERIAL: NO-80-1126

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street, N. W.
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
LICENSE NO. DPR-23
DOCKET NO. 50-261
RESPONSE TO IE BULLETIN 79-03A

Dear Mr. O'Reilly:

In response to your letter of April 4, 1980, transmitting IE Bulletin 79-03A concerning longitudinal weld defects in ASME SA-312, Type 304 stainless steel pipe, Carolina Power & Light Company submits the following information:

Carolina Power & Light Company has only recently received the background information necessary to perform an engineering evaluation of the impact of this bulletin on our Robinson Plant. This evaluation cannot be completed by the original due date of the bulletin, August 6, 1980.

Carolina Power & Light Company will provide you with the required information by September 22, 1980. Should you have any questions regarding this information, please contact my staff.

Yours very truly,

B. J. Furr
B. J. Furr
Vice President
Nuclear Operations

DCS:tma*

cc: Mr. Harold D. Thornburg

D